

HARTSDALE OFFICE SUPPLIES 014.440.6800 / F 6801 / 136618 / 2.5M • 11/16

PART NO	DESCRIPTION	SALE
	GASOLINE	21.38
1	IGNITION COIL	32.99
1	SET POINTS	3.29
1	FUEL PUMP	169.99
1	FUEL TANK SENDING UNIT	64.75
1	FUEL TANK TOP CRASKET	2.65
1	CLUTCH MASTER CYLINDER	177.30
1	CLUTCH SLAVE CYLINDER	92.75
1	IGNITION SWITCH	104.38
1	IGNITION LOCK	24.69
1	Needle and Seat Assembly	10.99
	SHIPPING	11.86
	SHIPPING	9.50
	CLEARANCE	7.50
		<b>624.42</b>

NOTE: CLUTCH HYDRAULICS AND IGNITION SWITCH PARTS BILLED OUT BUT NO INSTALLATION

**BRIARCLIFF**  
**CLASSIC IMPORTED**  
 CAR SERVICE LTD.

41122  
 90 WOODSIDE AVENUE  
 BRIARCLIFF MANOR, NY 10510  
 TEL (914) 762-1200  
 R260 1240  
 bcicarservice@verizon.net  
 briarcliffclassic.com

DATE 2/7/19  
 VIN 1U199  
 ENG# 7E1437-9  
 Bus 917-751-5200  
 Res 212-633-6952

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees, permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereon. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Authorized By \_\_\_\_\_

Name **COOPER CLASSICS**  
 Address **(ELLIOT CUKER)**  
 City \_\_\_\_\_  
 State \_\_\_\_\_  
 Zip \_\_\_\_\_  
 Year Make-Model **65 JAGUAR XKE** License No **N/A** Odometry **84510**

OPER NO. \_\_\_\_\_ REPAIR ORDER-LABOR INSTRUCTION \_\_\_\_\_ INTERNAL \_\_\_\_\_

CHARGE BATTERY. DISCOVER DISCONNECTED WIRES AT IMPROPER IGNITION SWITCH. TRACE WIRES AND RECONNECT. CHECK FOR FUEL BEING DELIVERED TO FUEL RAIL AT CARBUROTERS. CHECK FOR POWWR AND GROUND AT FUEL PUMP. INSTALL FUEL IN TANK. GET FUEL TO CARBUROTERS.

12 HRS UP TO 2/11 AND INCLUDING 12 HRS

CHECK FOR NO SPARK. REMOVE AND REPLACE IGNITION POINTS. REMOVE AND REPLACE IGNITION COIL TO PROPER SCREW IN TYPE. REPAIR IGNITION WIRE FROM COIL TO CAP. REMOVE AND REPLACE FUEL PUMP. CHECK POWER AND GROUND TO PUMP. REMOVE TANK PICK-UP TO CHECK FOR FUEL OUT LET. CLEAR AND BLOW OUT LINES. ENSURE FUEL GETTING TO FUEL RAIL. CHECK AND BLOW OUT SCREENS AT FLOAT BOWL TOPS. CLEAN OUT NEEDLE AND SEATS AT FLOAT BOWL TOPS. REMOVE CARBUROTOR DAMPER TOPS. CLEAN PISTONS AND NEEDLES. CLEAR OUT CARB. MAIN JETS. CLEAN GROUNDS FOR FUEL PUMP.

REMOVE PICK UP TUBE FROM TANK. CLEAR (INCLUDED PICK UP TUBE. REPLACE GASKET FOR PICK UP ASSEMBLY. REMOVE, CHECK AND REPLACE FUEL LEVEL SENDER. DISCOVER LOOSE CRANK SHAFT DAMPER RETAINING NUT-TIGHTEN. CHECK FOR NO FUEL IN REAR CARBUROTOR. REPLACE FRONT NEEDLE AND SEAT. CAR STARTS ON KEY!

1680.00

RECOMMENDED SERVICE:		TOTAL LABOR
1		1680.00
2		624.42
3		64.42
4		R/S
5		TOTAL AMOUNT 2304.42

Any warranties on the products sold hereby are those made by the manufacturer. The seller (above named dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

HARTSDALE OFFICE SUPPLIES 914 448 8500 / F 0801 / 136618 / 2.5M • 11/16

PART NO.	DESCRIPTION	SALE
1	DP. SWITCH	1495
1	HORN BASS	7990
	SHAWN	1000
		10485

40821

**BRIARCLIFF**  
**CLASSIC & IMPORTED**  
**CAR SERVICE LTD.**

90 WOODSIDE AVENUE  
 BRIARCLIFF MANOR, NY 10510  
 TEL (914) 762-1200  
 R260 1240

bccarservice@verizon.net  
 briarcliffclassic.com

DATE 4/12/14

VIN \_\_\_\_\_

ENG# \_\_\_\_\_

PHONE  
 Bus \_\_\_\_\_  
 Res \_\_\_\_\_

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees, permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Authorized By \_\_\_\_\_

Name **COOPER CLASSICS**

Address \_\_\_\_\_ Act No \_\_\_\_\_

City \_\_\_\_\_

Year-Make-Model **05 JAGUAR XKE** License No **N/A** Odometer **84510**

OPER NO.	REPAIR ORDER-LABOR INSTRUCTION	INTERNAL
	CHECK FOR LOW FUEL LEVEL LIGHT, CHECK WIRING AT TANK, DISCOVER WRONG BULB HOLDER (FOR IGNITION LIGHT) IN LOW FUEL METERING; SWAP BULB HOLDERS	
3 hrs	CHECK ALTERNATOR OUT PUT, CHECK WIRING TO ALTERNATOR AND ALTERNATOR WARNING LIGHT SYSTEM; TRACE PROBLEM TO DEFECTIVE OIL PRESSURE SWITCH;	100.00
	CHECK FOR NO HORN; CHECK WIRING AT STEERING COLUMN AND HOOK UP	
	CHECK FOR CLUNK IN STEERING; TIGHTEN UP LOOSE HARDWARE AT COLUMN UNDER DASH;	
	REMOVE STEERING WHEEL, STRAIGHTEN WHEEL AND RE-FIT; ROAD TEST	
	MOUNT AND BALANCE 4 TIRES;	
	Remove and replace Battery	
	ROAD TEST REARWIST IDLE	
	CREDIT ON HOOD REPAIR	-200.00

**RECOMMENDED SERVICE:**

TOTAL LABOR	500.00
PARTS	104.85
SUB TOTAL	604.85
SALES TAX	AS
TOTAL AMOUNT	604.85

Any warranties on the products sold hereby are those made by the manufacturer. The seller (above named dealership) hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products.

\* 20.02

1388

HARTSDALE OFFICE SUPPLIES 914 449 6500 / F 6801 / 136616 / 2.5M \* 11/16

PART NO	OR DESCRIPTION	SALE
1	BRAKE (CLUTCH) TUBE	600
	BRAKE FLUID	30.00
2	RESEVOIR BOTTLES	30.00
	BRAKE RESEVOIR HOSE CR606	10.00
	CLAMPS HOSE	9.00
	EXHAUST CLAMPS	19.80
	VARIOUS SHIPPING CHARGES	40.85
1	FAN SWITCH	48.00
1	" " WASHER	58
	RETURN ON INCORRECT PARTS	11.99
	GASOLINE	33.00
	SHIPPING	10.00
	MR. DENT	200.00
1	CLAVIS PIN	1.20
3	PT. TOP PAINT W/ SHIPPING	34.00
3	CARBURETOR DIAPHRAGMS	116.97
	CARBURETOR CLENER	7.95
4	HAMB PEGS	609.34
		684
3	ESCUCHION ASSEMBLIES	284
		744.64
TOTAL PARTS		

BRIARCLIFF  
**CLASSIC & IMPORTED**  
 CAR SERVICE LTD.  
 41130  
 90 WOODSIDE AVENUE  
 BRIARCLIFF MANOR, NY 10510  
 TEL. (914) 762-1200  
 R260 1240  
 bcicarservice@verizon.net  
 briarcliffclassic.com

Name: **COOPER CLASSICS**  
 Address: \_\_\_\_\_  
 City: \_\_\_\_\_  
 State: \_\_\_\_\_  
 Zip: \_\_\_\_\_  
 Year Make Model: **65 JAGUAR XKE** License No: **N/A** Odometer: **84510**

DATE: **2/23/79**  
 VIN: **10199**  
 ENG#: **7E1437-9**  
 P Bus \_\_\_\_\_  
 H \_\_\_\_\_  
 O \_\_\_\_\_  
 N \_\_\_\_\_  
 E \_\_\_\_\_  
 I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.  
 Authorized By: \_\_\_\_\_

OPER NO	REPAIR ORDER-LABOR INSTRUCTION	INTERNAL
2/12 36	Remove and Replace Ignition Switch and Secure Wires	
2/13 36	Remove HYDRAULIC FLUID RESEVOIR BOTTLES, REPLACE FEED HOSES UNDER NEATH; DISCONNECT TWO PLASTIC BOTTLES	
2/14 3	CRACKED Replace BOTH BRAKE FLUID RESEVOIR BOTTLES	
2/15 7	Remove and Replace CLUTCH MASTER CYLINDER AND SLAVE CYLINDER; REMOVE, FABRICATE AND REPLACE HARD LINE GOING TO SLAVE CYLINDER;	3360.00
2/18 4	FILL RESEVOIRS BLEED OUT BRAKES, REMOVE FROZEN CALIPER PISTON ASSEMBLY ON LEFT FRONT TO FREE UP AND REINSTALL; FREE UP PADS AND PISTON ASSEMBLIES IN REMAINDER OF FRONT AND COMPLETE BRAKE BLEEDING; CLEAN UP BRAKE ROTORS AS BEST POSSIBLE	
2/18 4	INSTALL MISSING CLAMPS ON EXHAUST; LUBRICATE CHASSIS, CHECK AND TOP UP TRANSMISSION AND DIFFERENTIAL;	
2/18 4	ATTEMPT TO TUNE CARBURETOR; DISCONNECT FROZEN CARBURETOR JETS; REMOVE CARBURETOR, DISASSEMBLE, CLEAN, RE-PLACE CARBURETOR JETS, FREE-UP CHOKE LINKAGE; REEF CARBURETOR, ADJUST LINKAGE; SYNCHRONIZE CARBURETOR OPENING; SET PRELIMINARY MIXTURE, SET 106 AND HIGH 106, CHECK 106 HANGING UP DISCONNECT LINKAGE AT FIRE WALL, CLEAN, LUBRICATE AND ADJUST; STRAIGHTEN CLUTCH PEDAL AS BEST POSSIBLE	

- RECOMMENDED SERVICE:
1. Wipe Arms + Blades
  2. Washer Bottle
  - 3.
  - 4.
  - 5.

TOTAL LABOR	3360.00
PARTS	744.64
SUB TOTAL	4104.64
SALES TAX	85
TOTAL AMOUNT	4104.64

Warranties on the products sold hereby are those made by the manufacturer (above named dealership) hereby expressly disclaims all warranties, express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person any liability in connection with the sale of said products.

Hudson Valley Auto Interiors  
 COMPLETE & PARTIAL RESTORATION  
 400 STATE STREET  
 SAUGERTOWN, NEW YORK 12587

6965

DATE OF ORDER: 2/19/19  
 MAKE & MODEL: 1965 Jaguar XKE

to Cooper Classics

DESCRIPTION	AMOUNT
Install Customer Supplied Convertible Top and Top Frame Gaskets Paint Convertible Top Frame Recover Front Bow with Black Vinyl Install Door Panels	\$ 2550 -

Change Wood in Front of Front Bow Replacing Front Bow Latch Screws	\$1450 -
---	----------

NO.	QUANTITY	UNIT PRICE	AMOUNT	TOTAL MATERIAL	TOTAL LABOR	TAX
				PAY THIS AMOUNT →		

I hereby acknowledge the satisfactory completion of the work described herein.

ENG# \_\_\_\_\_  
 P H O N E  
 Bus. \_\_\_\_\_  
 Res. \_\_\_\_\_

Name Cooper CLASSICS  
 Address \_\_\_\_\_ Apt. No. \_\_\_\_\_  
 City \_\_\_\_\_  
 Year-Make-Model \_\_\_\_\_ License No. \_\_\_\_\_ Odometer \_\_\_\_\_

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees, permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

Authorized By \_\_\_\_\_

**OPER NO.** \_\_\_\_\_ **REPAIR ORDER-LABOR INSTRUCTION** \_\_\_\_\_ **INTERNAL** \_\_\_\_\_

$\frac{1}{2}$  } CHECK FOR NO GAUGE LIGHTS, CHECK AND RE-WIRE SWITCH, FURTHER CHECK OF LIGHTS, - Replace 3 GAUGE ILLUMINATION BULBS.  
 } CHECK FOR 'Jumpy' AMMETER GAUGE; CHECK FOR PROBLEM AT ALTERNATOR, DETERMINING GAUGE IS PROBLEM;  
 } CHECK OPERATION OF HEATER BLOWER MOTOR;  
 } ADJUST IDLE  
 } TUCK WIRES UNDER DASH  
 } CHECK CHOKE CABLE ADJUSTMENT  
  
 $\frac{1}{2}$  Remove AND replace HEATER BLOWER MOTOR, Remove 'CASE', MODIFY BLOWER MOTOR SHAFT TO ACCEPT CASE

N/C  
 N/C  
 N/C

**RECOMMENDED SERVICE:**

- 1.
- 2.
- 3.
- 4.
- 5.

TOTAL PARTS

TO PAY

warranties on the products sold hereby are those made by the manufacturer. seller (above named dealership) hereby expressly disclaims all warranties, express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person assume for it any liability in connection with the sale of said products.