

★ CODE N-NEW U-USED R-REBUILT M-OEM				
QTY	★	PART NO OR DESCRIPTION		SALE
1	N	Lower Hoxe		4830
1	N	Upper Hoxe		3950
1	N	Red pass Hoxe		1250
2	N	Coolant		3400
2	N	Water pump Belt		3400
8	N	Plugs		4000
1	N	Oil Filter		3750
1	R	Water pump		63900
1	U	Water pipe		22500
2	N	Brake Boots Seal		4880
1	N	Driver door Seal		8500
1	N	Fuel Pump		24000
2	N	Fuel Pump Filter		1800
1	N	Rear Brake Hoxe		5900
2	N	Front Brake Hoxe		11000
1	N	Front Brake pads		7498
1	N	Head Gasket Set		51510
4	N	Coilover Kit	4230	16920
1	N	Clutch Slave		8500
1	N	Clutch Master		21733
1	N	Brake Master Kit		5991
1	N	Rear Brake pads		4234
4	N	Rear Coilover Piston	1500	18000
2	N	Coilover Piston	4700	9400
4	N	Rear Coilover Kit		6500
2	N	Coilover Piston	1500	18000
MATERIALS AND SUPPLIES				328246
TOTAL PARTS				
WARRANTIES				
adverse \$2,000.00 PK 1090				
adverse \$2,000.00 PK 703				
SPECIAL REPAIRS				
		Radiator Rattlehead Repair	22000	
		Body Work	30000	
		Tires	15780	
		SHAPING	1110	
TOTAL SPECIAL REPAIRS				98890

ALFA ITALIA INC.

EUROPEAN IMPORT CARS SERVICE
1700 N. SAN FERNANDO BLVD., BURBANK, CA 91504
(818) 841-6959 • (323) 849-4595

Date	11-30-17	4496	
Time Received	AM PM	OPERATION	LAB. CHG.
Promised	AM PM	Lubrication	
Written By		Change Oil	
Cust Order No		Change Oil Filter Cart	
Phone when ready	Yes <input type="checkbox"/> No <input type="checkbox"/>	Service Air Cleaner	
		Change Trans Oil	
		Adjust Transmission	
		Hazardous Waste	
		Pack Wheel Brgs	
		Rotate Tires	
		Adjust Brakes	
		Retain Parts	
		Destroy Parts	

Name: Joel Shapiro

Address: _____ City: _____

Vin. No: _____

Year-Make-Model: 1971 Mercedes 280SL License No: 4N000 Odometer: 72911

ESTIMATE AMT. _____

ADD'L AUTH. AMT _____

REVISED ESTIMATE _____

DATE: _____ APPROVED BY: _____

TIME: _____ ☐ IN PERSON ☐ PHONE

Authorized By: _____

I ACKNOWLEDGE NOTICE AND ORAL AP-
PROVAL OF AN INCREASE IN THE ORIGINAL
ESTIMATED PRICE (SIGNATURE OR INITIALS)

OPER NO.	REPAIR ORDER LABOR INSTRUCTION	INTERNAL
	Remove Cylinder Head For Replace	
	Head Gasket replace Water Passag.	2,200.00
	adjust Valve and Reinstall	
	Remove and install Gas Tank and Pumps	330.00
	Rebuilt Carburetor Replace Fuel Hose	
	and adjust and Replace Fuel Pump	550.00
	Repair cooling Fan Sprockets	
	Replace clutch Master Cylinder and slave	220.00
	Replace Driver door Seal	55.00
	Remove Radiator Replace Water pump	550.00
	Replace Hoses Repair Water Inlet Damage	
	Front Right Head Light Housing	220.00
	Remove For Repair and Install	
	TOTAL LABOR	4725.00
	TEARDOWN ESTIMATE - PARTS AND LABOR	
	ORIGINAL ESTIMATES	
	AUTHORIZED BY	
	PHONE DATE TIME	
	REASON	
	REVISED ESTIMATES	
	OK'D BY	
	ADDITIONAL COSTS	
	AUTHORIZED BY	
	IN PERSON PHONE #	
	DATE TIME	
	TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within _____ days of the date shown above if I choose not to authorize the services recommended.	
	INIT	
	Sales Tax	311.83
	TOTAL	9308.19

