

Arizona Bimmer

7255 E Adobe Dr. Ste. 120 Scottsdale, AZ 85255

Phone: 480-404-0051

Your Independent BMW Service and Repair Experts

12/28/2020 1:12:31 PM

Invoice # **2220**

ERIC SAUL

6744 E HORNED OWL TR Scottsdale, AZ 85266 Cell 480-241-1893 ERIC



1985 BMW 528e

Odometer In: 248994

License: 4FBZ248 - CA

VIN: WBADK7300F9356286

INVOICE

Key 36

Performed Engine Oil Service

<u>Description</u>	<u>Quantity</u>	<u>Sale</u>	<u>Extended</u>
Liqui Moly High Tech LL-01 Fully Synthetic 5W-40 Engine Oil	7.00	\$8.70	\$60.90
Oil Filter	1.00	\$9.99	\$9.99

BMW Inspection: https://2un.me/kxweiene

Labor: \$25.00 **Parts:** \$70.89 **Sublet:**\$0.00 **Job Total:** \$95.89

A/C stopped working. Was working last week during buyers inspection.

Belt squeal on cold starts.

Shifter may feel loose?

Door lock issue. When using key in drivers door lock the other locks seem to make some noise but not activate...

RF door wont open from inside

Headlights not working?

Interior backlight switch seems loose.

viccii seeilis 1003	- -				
<u>Description</u>			<u>Quantity</u>	<u>Sale</u>	Extended
/lxkeielf					
vice .					
heck condition of all	belts and lines. Evacuate a	nd recharge with R-134. Test system	performance.		
<u>Description</u>			<u>Quantity</u>	<u>Sale</u>	Extended
R134a Refrigerant	t		1.50	\$16.41	\$24.62
A/C Switch			1.00	\$129.12	\$129.12
	Parts: \$153.74	Sublet: \$0.00		Job Tot	al: \$263.74
or light/fog light	switch.				
Description			Quantity	<u>Sale</u>	Extended
Switch Cover			1.00	\$47.35	\$47.35
	Parts: \$47.35	Sublet:\$0.00		Job Tot	al: \$102.35
up of p/s res hos	es				
Description			Quantity	<u>Sale</u>	Extended
Parts Cleaner			1.00	\$20.00	\$20.00
	Description //lxkeielf /rice heck condition of all Description R134a Refrigerant A/C Switch or light/fog light Description Switch Cover	Description //Ixkeielf /rice heck condition of all belts and lines. Evacuate a Description R134a Refrigerant A/C Switch Parts: \$153.74 or light/fog light switch. Description Switch Cover Parts: \$47.35 up of p/s res hoses Description	Description //Ixkeielf /rice heck condition of all belts and lines. Evacuate and recharge with R-134. Test system Description R134a Refrigerant A/C Switch Parts: \$153.74 Sublet:\$0.00 or light/fog light switch. Description Switch Cover Parts: \$47.35 Sublet:\$0.00 up of p/s res hoses Description	Description Vixkeielf vice heck condition of all belts and lines. Evacuate and recharge with R-134. Test system performance. Description R134a Refrigerant A/C Switch Parts: \$153.74 Sublet:\$0.00 or light/fog light switch. Description Switch Cover Parts: \$47.35 Sublet:\$0.00 up of p/s res hoses Description Ouantity Available to the cover of the cove	Description Vixkeielf Vice heck condition of all belts and lines. Evacuate and recharge with R-134. Test system performance. Description R134a Refrigerant A/C Switch Parts: \$153.74 Sublet: \$0.00 Sublet: \$0.00 Total light/fog light switch. Description Switch Cover Parts: \$47.35 Sublet: \$0.00 Job Total sale \$47.35 Parts: \$47.35 Sublet: \$0.00 Sublet: \$0.00 Duantity \$28e \$47.35 \$47.35 \$47.35 \$47.35 \$47.35 \$47.35 \$47.35 \$48e \$48





Arizona Bimmer

7255 E Adobe Dr. Ste. 120 Scottsdale, AZ 85255

Phone: 480-404-0051

Your Independent BMW Service and Repair Experts

12/28/2020 1:12:31 PM

Invoice # **2220**

ERIC SAUL

6744 E HORNED OWL TR Scottsdale, AZ 85266 Cell 480-241-1893 ERIC



1985 BMW 528e

Odometer In: 248994

License: 4FBZ248 - CA

VIN: WBADK7300F9356286

INVOICE						
		Сол	ntinued From Previous Page			
	Hose Clamp - Norma	a 16-28 mm		3.00	\$3.03	\$9.09
Labor: \$55.00	Labor: \$55.00 Parts: \$29.09 Sublet: \$0.00			Job Total: \$84		
ALTERNATOR DRI	VE BELT - Remove &	Replace - All Applic	able Models - [Includes: Serpe	entine and		
V-Belt type Belt(s)).]					
	<u>Description</u>			Quantity	Sale	Extended
	Drive Belt-Air Condit	tioning ContiTech V-Be	lt	1.00	\$20.88	\$20.88
	Drive Belt-Alternator	r ContiTech V-Belt		1.00	\$31.56	\$31.56
	Drive Belt-Power Ste	eering ContiTech V-Bel	t	1.00	\$20.16	\$20.16
Labor: \$99.00	0 Parts: \$72.60 Sublet: \$0.00				Job Total: \$171.60	
Replace worn shif	t tower mounting bu	shing				
	<u>Description</u>			Quantity	<u>Sale</u>	Extended
	Shift Tower Mount			1.00	\$12.08	\$12.08
Labor: \$110.00		Parts: \$12.08	Sublet: \$0.00		Job Tot	al: \$122.08
OUTPUT FLANGE S	SEAL - Remove & Rep	olace - All Applicable	Models			
	<u>Description</u>			Quantity	Sale	Extended
	Output Shaft Seal			1.00	\$23.73	\$23.73
	Shift Rod Seal			1.00	\$23.85	\$23.85
	Gear Oil 75W-90 GL	-5 1L		2.00	\$24.25	\$48.50
	Parts Cleaner			1.00	\$20.00	\$20.00
	Transmission Mount	:		2.00	\$39.36	\$78.72
Labor: \$330.00		Parts: \$194.80	Sublet:\$0.00		Job Tot	al: \$524.80





Arizona Bimmer

7255 E Adobe Dr. Ste. 120 Scottsdale, AZ 85255

Phone: 480-404-0051

Your Independent BMW Service and Repair Experts

12/28/2020 1:12:32 PM

Invoice # 2220

ERIC SAUL

6744 E HORNED OWL TR Scottsdale, AZ 85266 Cell 480-241-1893 ERIC



1985 BMW 528e

Odometer In: 248994 License: 4FBZ248 - CA

VIN: WBADK7300F9356286

INVOICE

Continued From Previous Page

Recommendations

09/24/2021 Perform Next Lube, Oil & Filter Exchange on 9/24/2021 or 254000 Miles.

09/25/2020 Replace faulty LR door lock actuator (part must be ordered from germany) \$260.

09/25/2020 Brake fluid system flush every 2 years \$135.

09/25/2020 Reseal and clean up of leaking valve cover \$267.

10/21/2020 Adjusted Cigarette Lighter during this visit. 10/21/2020 Replace Evaporator Temp Sensor: \$371 10/21/2020 Replaced Interior Light Control Relay: \$141

Customer Authorization	Authorized By	Previous Est.	Add'l Cost	Revised Est.	
9/29/20 10:35	SAUL, ERIC	\$110.00	\$284.52	\$394.52	
Parts: \$153.74 Labor: \$110.00 Sublet: \$0.00 Taxes & Fees: \$20.78 Written bv:	Fouts, Nick Initiated Bv: Shop	Cell: 480-241-1893xERIC			
9/29/20 10:35	SAUL, ERIC	\$386.12	\$114.56	\$500.68	
Parts: \$47.35 Labor: \$55.00 Sublet: \$0.00 Taxes & Fees: \$12.21 Written bv: Fo	outs. Nick Initiated Bv: Shop Ce	ell: 480-241-1893xERIC			
9/29/20 10:36	SAUL, ERIC	\$492.28	\$94.83	\$587.11	
Parts: \$29.09 Labor: \$55.00 Sublet: \$0.00 Taxes & Fees: \$10.74 Written by: Fo	outs, Nick Initiated By: Shop Ce	ell: 480-241-1893xERIC			
9/29/20 10:36	SAUL, ERIC	\$578.71	\$317.30	\$896.01	
Parts: \$84.68 Labor: \$209.00 Sublet: \$0.00 Taxes & Fees: \$23.62 Written bv: Fouts. Nick Initiated Bv: Shop Cell: 480-241-1893xERIC					
9/29/20 10:40	SAUL, ERIC	\$879.21	\$548.88	\$1,428.09	

Parts: \$194.80 Labor: \$330.00 Sublet: \$0.00 Taxes & Fees: \$24.08 Written by: Fouts. Nick Initiated By: Shop Cell: 480-241-1893xERIC

Service Advisor: Fouts, Nick

Technician(s): Eric, Alcazar; Fouts, Nick

I consent to receiving text messages regarding your services, via automated technology, to the cell phone number you have on file. I acknowledge that I do not have to provide this consent to receive your services. Message and data rates may apply. Respond STOP to any message to cancel.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is two years or 24,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Labor Total:	\$784.00
Parts Total:	\$580.55
Sublet Total:	\$0.00
Shop Sup:	\$5.00
HazMat:	\$3.00
Sub Total:	\$1,372.55
Tax Total:	\$47.14
Grand Total:	\$1,419.69
Balance Due:	\$0.00







SIGNATURE.....

October 7, 2020 4:50 pm

Payment(s)

10/7/2020 4:50:22PM

\$1,419.69

Elec - Credit Card

Auth:

SALE:025019:160699040::1568170712:Y:: 1568170712-Visa-3042





