

Birdie's Speed Shop

828 Harding Avenue

North Tonawanda, NY. 14120

Phone: 716-692-6272 Fax: 716-692-6272

Automotive Sales and Service

INVOICE**2631**

7097344

INVOICE

Work Completed : 07/24/2020

Date: 09/21/2020

Hirsch, Tracy

8191 Cole Road

Colden, NY 14033

Cellular 716-725-4654 -- Office 716-649-8919

2002 Bentley - Arnage T - 6.8L 6750CC 412Cu V8 GAS OHV Tw

Lic # : B440

Odometer In : 41262

VIN # : SCBLF34F0 2CX08779

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Bentley Interior Door Panel Trim Card Stud Fastener Clips OE Dealer DPC	12.00	2.99	35.88	Birdie's Speed Shop Ceramic Pro Exterior Package Includes Interior, Exterior, and Wheels	1,900.00
Window Motor / Regulator Drivers / LEFT- REAR Dealer Part OE Bentley WRM	1.00	1,495.00	1,495.00	OEM Paint Color: #9560022 Silver Tempest Mica	n/c
Serpentine Belt BLT	1.00	149.84	149.84	Remove Door Panel and Test Components Electrical Testing Driver's Rear Window Window Regulator / Motor non operable Advise Customer of Findings	150.00
Front Pads - OE Ceramic - Premium FP	1.00	0.00	n/c	Remove and Install Left Hand Rear (Driver's Rear) Window Motor / Regulator	265.00
Rear Pads - OE Ceramic - Premium RP	1.00	0.00	n/c	Headlight Lens Adjustment - FRONT Left and Right Headlights	100.00
Solenoid Valve Secondary Air Injection OEM Dealer Part SVSAI	1.00	0.00	n/c	Remove and Install Serpentine Belt	320.00
Emission Control Air Injection Valve OEM Dealer Part ECAIV	1.00	0.00	n/c	Remove and Install Rear Pads Clean, Lubricate, and Adjust Calipers - Left and Right FRONT Included Premium Pads - Front	450.00
Intake Valve Gaskets OE Dealer Bentley IVG	2.00	49.89	99.78	Remove and Install Rear Pads Clean, Lubricate, and Adjust Calipers - Left and Right REAR Includes Premium Pads - Rear	450.00
Vacuum Hose VH	1.00	0.00	n/c	Diagnostic Scan - Testing and Evaluation : Codes Present: P0491 and P0492 Secondary Air Insufficient Flow	150.00
Fuse 30 AMP FSE	1.00	0.00	n/c	Drive To Reset Monitors to pass NYSI w/ Diagnostic Scanner	250.00
Coolant ANT	2.00	18.99	37.98	NYS Safety & Emission Inspection	21.00
				Total Package: Secondary Air Injection Service and Repair Includes Labor and Parts (Discounted)	4,100.00
				Remove Intake Manifold and Inter Coolers for Access Above Transmission.	n/c
				Remove and Install Solenoid Valve Secondary Air Injection Remove and Install Emission Control Air Injection Valve	n/c
				Remove and Install Intake Valve Gaskets (Two)	n/c
				Remove and Install Vacuum Line Rear of Engine	n/c
				Remove and Install Fuse 30 AMP Found Fuse Blown Replace	n/c
				Flush Coolant System	n/c



CL #
5793

Birdie's Speed Shop

828 Harding Avenue

North Tonawanda, NY. 14120

Phone: 716-692-6272 Fax: 716-692-6272

Automotive Sales and Service

INVOICE**2631**

7097344

INVOICE

Work Completed : 07/24/2020

Date: 09/21/2020

Hirsch, Tracy

8191 Cole Road

Colden, NY 14033

Cellular 716-725-4654 -- Office 716-649-8919

2002 Bentley - Arnage T - 6.8L 6750CC 412Cu V8 GAS OHV Tw

Lic # : B440

Odometer In : 41262

VIN # : SCBLF34F0 2CX08779

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----

Vehicle Notes:

** Headlight Adjuster Knobs are worn out / making them adjustable.

** Dump Valve - Bentley Dealership informed us that the part is discontinued.

** Many parts are discontinued for the Arnage



Vehicle Evaluation / Customer requests NYSI:

Services / Repairs Found:

* Check Engine Light On / Secondary Air Injection System Codes P0491 & P0492

Remove Intake Manifold and Inter Coolers for Access Above Transmission. Needs Secondary Air Injections Parts

* Brakes - Low / Front and Rear | Rotors at minimum Spec but grooved.

* Left Rear Window In-operable - Needs Diagnosis / Found need replacement - Motor and Regulator

* Headlights Need Proper Adjustment / Alignment

* Serpentine Belt / Cracked - Dry-rotting

* Body / Paint Correction and Ceramic Pro - Recommended Service

PAID
Check # 5793

Org. Estimate 2,165.40 Revisions 0.00 Current Estimate 2,165.40

Labor:	8,156.00
Parts:	1,818.48
SubTotal:	9,974.48
Tax:	796.28
Total:	10,770.76
Bal Due:	\$10,770.76

[Payments -]

Vehicle Received: 6/18/2020

Customer Number : 666

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Signature 

Date

9/22/2020

Visit us on the web: www.birdiesspeedshop.com

Email Address: birdiesspeedshop@roadrunner.com