



David Nutley Automotive
 BAR Registration No. ARD298541
 EPA Identification No. CAL000461491
 5155 Convoy Street, Suite B
 San Diego, CA 92111
 (858) 774-4734
 admin@dn-automotive.com

Invoice #1331

Created: 1/25/2022 10:38 AM PST
 Invoiced: 2/10/2022 12:51 PM PST
 Service Writer: Erika Smith

J&E Ellison Family LTD Partnership

7012 Rancho La Cima Drive
 Rancho Santa Fe, CA 92067
 Mobile: (760) 535-1258
 john.ellison.jr@att.net

1994 ROLLS ROYCE Silver Spur (White)

VIN: SCAZN02C0RCX54213
 Mileage In: 48,676
 Mileage Out: 48,684
 PSI: FL 30 FR 30 RL 32 RR 32

Customer Comments	Recommendations
Dent at rear of trunk Right rear door window stuck down Front brake calipers are leaking fluid Rear suspension hydraulic struts are leaking Problem with brake accumulators AC doesn't blow cold Airbag warning light on Antenna is stuck Interior lighting doesn't come on for all doors Passenger seat won't adjust. NFF=working at this time Gas refill door does not open (only manually) Working	Inquire with Auto Armour for "dent guy" contact info

Front brake calipers are leaking				
Description	Price	QTY	HRS	Subtotal
1 R&R and overhaul front brake calipers. Fit new pads			6	\$1,050.00
2 Caliper kit Part #: CD5972GMFR	\$90.85	1		\$90.85
3 Brake pads Part #: UR73208	\$445.93	1		\$445.93
4 O-ring Part #: A90025K137	\$3.75	8		\$30.00
5 Parts Cleaner Berrymans	\$13.18	1		\$13.18
6 Shipping				\$132.19
				Total: \$1,762.15

Hydraulic brake pumps are leaking				
Description	Price	QTY	HRS	Subtotal
1 Reseal both hydraulic brake pump sleeves. Clean affected area.			7	\$1,225.00
2 Brake pump reseal kits Part #: RH2897R	\$36.25	2		\$72.50
3 Feed pipe seal Part #: GMF1023R	\$3.75	2		\$7.50
4 Parts Cleaner Berrymans	\$13.18	1		\$13.18
				Total: \$1,318.18

Hydraulic brake pump feed hoses are leaking



David Nutley Automotive
BAR Registration No. ARD298541
EPA Identification No. CAL000461491
5155 Convoy Street, Suite B
San Diego, CA 92111
(858) 774-4734
admin@dn-automotive.com

Invoice #1331

Created: 1/25/2022 10:38 AM PST
Invoiced: 2/10/2022 12:51 PM PST
Service Writer: Erika Smith

Hydraulic brake pump feed hoses are leaking				
Description	Price	QTY	HRS	Subtotal
1 Replace pump feed hoses and insulation sleeves. Fit new clamps			2	\$350.00
2 Pump feed hose Part #: GMF1200R	\$78.20	1		\$78.20
3 Pump feed hose Part #: GMF1199R	\$76.19	1		\$76.19
4 Insulation sleeves Part #: UR70345R, UR22131R	\$15.00	1		\$15.00
5 Hose clamp Part #: Various size	\$2.65	4		\$10.60
				Total: \$529.99

Brake accumulators are partially depressurized				
Description	Price	QTY	HRS	Subtotal
1 Replace brake spheres and seals			1.5	\$262.50
2 Brake spheres Part #: CD6000GMFR	\$109.25	2		\$218.50
3 Sphere seals Part #: GMF1225R	\$4.00	2		\$8.00
				Total: \$489.00

Accumulator return hoses are leaking				
Description	Price	QTY	HRS	Subtotal
1 Replace accumulator return hoses and insulation sleeves.			5	\$875.00
2 Accumulator return hose Part #: GMF1313R	\$113.45	1		\$113.45
3 Accumulator return hose Part #: GMF1299R	\$136.85	1		\$136.85
4 Hose clamp Part #: Various size	\$2.65	4		\$10.60
				Total: \$1,135.90

Brake distribution cover has fluid leaking				
Description			HRS	Subtotal
1 R&R distribution cover and identify location of leak. Clean cover			1	\$175.00
				Total: \$175.00

All brake hoses are original				
Description	Price	QTY	HRS	Subtotal



David Nutley Automotive
 BAR Registration No. ARD298541
 EPA Identification No. CAL000461491
 5155 Convoy Street, Suite B
 San Diego, CA 92111
 (858) 774-4734
 admin@dn-automotive.com

Invoice #1331

Created: 1/25/2022 10:38 AM PST
 Invoiced: 2/10/2022 12:51 PM PST
 Service Writer: Erika Smith

All brake hoses are original				
1	Replace all brake hoses due to age. 8 years is the life span for these hoses		6.5	\$1,137.50
2	Front brake hose Part #: GMF1323R	\$63.10	2	\$126.20
3	Rear brake hose Part #: GMF1324R	\$51.75	4	\$207.00
4	Leveling hose Part #: GMF1218R	\$111.38	1	\$111.38
				Total: \$1,582.08

Rear hydraulic struts are leaking					
	Description	Price	QTY	HRS	Subtotal
1	Replace both rear struts, mounts and drain tubes			6	\$1,050.00
2	Strut Part #: GMF1311R	\$715.00	2		\$1,430.00
3	Sphere seal Part #: GMF1225R	\$2.50	2		\$5.00
4	Gas spring Part #: GMF1106R	\$119.60	1		\$119.60
5	Housing seal Part #: GMF 1262	\$4.45	2		\$8.90
					Total: \$2,613.50

Interior lights do not work with all doors					
	Description	Price	QTY	HRS	Subtotal
1	Left rear door is not turning on interior lights. Remove door panel to gain access to micro switch and test			2.3	\$402.50
2	Micro switch CDL Part #: UD7343R	\$142.60	1		\$142.60
					Total: \$545.10

Exhaust support bracket hardware is missing					
	Description			HRS	Subtotal
1	Fit required hardware for catalytic converter support and adjust.			0.5	\$87.50
					Total: \$87.50

Drive belts are loose and cracked					
	Description	Price	QTY	HRS	Subtotal
1	Replace engine drive belts			3.5	\$612.50



David Nutley Automotive
 BAR Registration No. ARD298541
 EPA Identification No. CAL000461491
 5155 Convoy Street, Suite B
 San Diego, CA 92111
 (858) 774-4734
 admin@dn-automotive.com

Invoice #1331

Created: 1/25/2022 10:38 AM PST
 Invoiced: 2/10/2022 12:51 PM PST
 Service Writer: Erika Smith

Drive belts are loose and cracked				
2	Air pump belt Part #: SPC3722	\$28.16	1	\$28.16
3	A/C compressor belt Part #: SPC3682	\$62.80	1	\$62.80
4	Alternator belt	\$46.34	1	\$46.34
5	PAS belt set	\$127.03	1	\$127.03
				Total: \$876.83

Complete fluid service					
	Description	Price	QTY	HRS	Subtotal
1	Perform complete fluid service. Engine oil and filter, transmission service, differential oil service, flush hydraulic system, flush cooling system			4	\$700.00
2	RR Oil filter Part #: 07V121717A	\$40.04	1		\$40.04
3	20w50 Engine Oil Part #: LM20114	\$11.23	9		\$101.07
4	RR Drain plug washer Part #: WHT002909R	\$2.20	3		\$6.60
5	85w90 Liqui Moly Hypoid Part #: LM 20010	\$18.55	2.75		\$51.01
6	Dexron III Transmission oil Part #: 88865544	\$8.08	5		\$40.40
7	Hydraulic mineral fluid Part #: RH15215R	\$18.75	5		\$93.75
8	Coolant (Green) Part #: WP-851742	\$16.88	2		\$33.76
9	Radiator drain plug	\$8.65	2		\$17.30
10	MOC washer fluid Part #: 61131	\$4.95	1		\$4.95
11	MOC parts wash Part #: MOC	\$5.99	1		\$5.99
					Total: \$1,094.87

Perform complete vehicle inspection and estimate repair items				
	Description		HRS	Subtotal
1	Perform complete vehicle inspection and estimate repair items		2	\$350.00
				Total: \$350.00

Dent in rear face of boot lid			



David Nutley Automotive
 BAR Registration No. ARD298541
 EPA Identification No. CAL000461491
 5155 Convoy Street, Suite B
 San Diego, CA 92111
 (858) 774-4734
 admin@dn-automotive.com

Invoice #1331

Created: 1/25/2022 10:38 AM PST
 Invoiced: 2/10/2022 12:51 PM PST
 Service Writer: Erika Smith

Dent in rear face of boot lid				
Description	Price	QTY	HRS	Subtotal
1 De-trim for pointless dent removal			0.5	\$87.50
2 Paintless dent removal	\$400.00			\$400.00
				Total: \$487.50

Right rear window is inoperative				
Description	Price	QTY	HRS	Subtotal
1 Remove door panel to access window motor. Remove window motor to inspect and repair drive system			3	\$525.00
2 Drive coupling Part #: UD71409R	\$21.60	1		\$21.60
				Total: \$546.60

Air conditioning does not blow cold				
Description	Price	QTY	HRS	Subtotal
1 Diagnose A/C system. Evacuate and charge system. Check for leaks and none found at this time. 53 degree duct temp=Good			2.5	\$437.50
2 R134a freon Part #: R143a	\$20.00	2.2		\$44.00
				Total: \$481.50

Airbag warning light is on				
Description			HRS	Subtotal
1 Diagnose airbag light. 2104 code logged for drivers squib. Clear fault and monitor for return of fault.			1	\$175.00
				Total: \$175.00

Radio antenna not fully extending				
Description			HRS	Subtotal
1 Free off antenna mast and clean. lubricate and ensure proper operation			0.2	\$35.00
				Total: \$35.00

Battery is incorrect				
Description	Price	QTY	HRS	Subtotal
1 Replace battery with correct amperage battery			0.5	\$87.50
2 MT-24	\$149.95	1		\$149.95
				Total: \$237.45



David Nutley Automotive
 BAR Registration No. ARD298541
 EPA Identification No. CAL000461491
 5155 Convoy Street, Suite B
 San Diego, CA 92111
 (858) 774-4734
 admin@dn-automotive.com

Invoice #1331

Created: 1/25/2022 10:38 AM PST
 Invoiced: 2/10/2022 12:51 PM PST
 Service Writer: Erika Smith

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature _____

Totals only include authorized services

Parts	\$4,365.96
Labor	\$9,625.00
Subcontract	\$400.00
Subtotal	\$14,523.15
Fees	\$132.19
Tax	\$0.00
Grand Total	\$14,523.15
Paid To Date	(\$14,523.15)

REMAINING BALANCE \$0.00

Payments			
3/18/2022	Credit card ending in 2000		\$9,523.15
2/7/2022	Cash	Deposit received for parts	\$5,000.00

Needs Response

Remove and refit rear parcel shelf panels for recovering			
Description		HRS	Subtotal
1 Remove and refit rear parcel shelf panels for recovering. R&R rear seats to do so.		2.5	\$437.50
			Total: \$437.50

Left rear wheel stud and nut missing, fit bellisher and new clips				
Description	Price	QTY	HRS	Subtotal
1 Fit replacement wheel stud and nut and fit all new bellisher clips and 1 new ring			1	\$175.00
2 Left wheel stud Part #: SPC3399	\$37.69	1		\$37.69
3 Left wheel nut Part #: UG4455	\$67.41	1		\$67.41
4 Wheel Clip plastic	\$3.39	24		\$81.36
5 Wheel Clip	\$6.84	19		\$129.96
6 Wheel Trim Ring	\$274.85	1		\$274.85
7 Shipping				\$60.76
				Total: \$827.03

Install new rear door speakers while door panels are off for repairs				
Description	Price	QTY	HRS	Subtotal



David Nutley Automotive
BAR Registration No. ARD298541
EPA Identification No. CAL000461491
5155 Convoy Street, Suite B
San Diego, CA 92111
(858) 774-4734
admin@dn-automotive.com

Invoice #1331

Created: 1/25/2022 10:38 AM PST
Invoiced: 2/10/2022 12:51 PM PST
Service Writer: Erika Smith

Install new rear door speakers while door panels are off for repairs			
1	Remove rear door speakers while other work is being performed. Disassemble speaker from housings and modify and fit new speakers. Rewire for new speakers	1	\$175.00
2	Rear speakers	\$75.00	1 \$75.00
			Total: \$250.00



David Nutley Automotive
 BAR Registration No. ARD298541
 EPA Identification No. CAL000461491
 5155 Convoy Street, Suite B
 San Diego, CA 92111
 (858) 774-4734
 admin@dn-automotive.com

Invoice #1480

Created: 5/19/2022 01:50 PM PDT
 Invoiced: 5/20/2022 08:51 AM PDT
 Service Writer: David Nutley

J&E Ellison Family LTD Partnership

7012 Rancho La Cima Drive
 Rancho Santa Fe, CA 92067
 Mobile: (760) 535-1258
 john.ellison.jr@att.net

1994 ROLLS ROYCE Silver Spur (White)

VIN: SCAZN02C0RCX54213
 Last Recorded Mileage: 48,684
 Mileage: 48,835

Customer Comments

Install new wheel ring and attach all with adhesive

Install new wheel ring and attach all with adhesive

Description	Price	QTY	HRS	Subtotal
1 Replace missing wheel ring, clean all rings and clips and secure all with adhesive.			0.75	\$131.25
2 Wheel trim ring Part #: UE71653R	\$274.85	1		\$274.85
Total:				\$406.10

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature _____

Parts	\$274.85
Labor	\$131.25
Subtotal	\$406.10
Tax	\$0.00
Grand Total	\$406.10
Paid To Date	(\$406.10)

REMAINING BALANCE \$0.00

Payments

5/20/2022	Visa	\$406.10
-----------	------	----------

EVANS TIRE & SERVICE CENTERS

Evans Tire & Service Centers
 330 N. El Camino Real
 Encinitas, CA 92024
 (760)942-2162

FREE OIL CHANGES / EXCLUSIVE DISCOUNTS & SPECIALS
 Text EVANSTIRE to 833-669-0337

Customer ID: 3114067691
 Name: JOHN ELLISON
 Address: NA
 Address 2:
 City,State,Zip Code: ENCINITAS, CA, 92024
 Home Phone: (760) 535-1258
 Work Phone: () -
 Mobile Phone: () -
 Tax Exempt #:

Year: 94
 Make: ROLLS-ROYCE
 Model: SILVER SPIRIT II
 Lic No: 36653
 VIN: 1
 Color: WHITE
 Engine: 1
 Mileage In: 48686
 Mileage Out: 48686

Create Date: 01/13/22 13:26:29
 Date/Time: 01/18/22 13:32:06
 Workorder #: 409352
 Invoice #: 227897
 Email Address: na
 PO Number:
 Fleet/Wholesale: N
 EPA #: CAL000440225
 BAR #: ARD00292322

Salesperson: R. CHIRIKDJIAN
 Service comments:

TIRE PRESSURE: LF 35 RF 35 LR 35 RR 35 SPARE NA
 TREAD DEPTH: LF 11/32 RF 11/32 LR 11/32 RR 11/32 SPARE NA/32
 BRAKE PAD THICKNESS: LF 8 RF 8 LR 8 RR 8

REVISED ESTIMATE AUTHORIZATION(S):

AUTH. BY: CONTACT: JOHN ELLISON ADD. AMT: 421.26
 DATE: 01-18-22 TIME: 8:22 AM PREVIOUS EST: 0.00 REV EST: 421.26

Work Authorized: 4 TIRES

APPROVED BY:  FINAL INVOICE APPROVAL: 

Qty.	Part #	RFR	Loc	Description	Parts	Labor	Total
4	24750005			MS775 Touring SLE MILE P225/75R15 SL102S SL WW	91.00	0.00	364.00
		2522	2522	DOT Numbers: 2522 2522 2522 2522			
4	TPP			TIRE PROTECTION POLICY	17.29	0.00	69.16
4	21-173			RUBBER VALVE STEM	2.99	0.00	11.96
4	MB			MOUNT & BALANCE TIRE	0.00	24.00	96.00
4	TDF			TIRE DISPOSAL FEE	6.50	0.00	26.00
4	CTDF			CALIFORNIA TIRE RECYCLING FEE	1.75	0.00	7.00
1	WRT				0.00	0.00	0.00
				CUSTOMER IS RESPONSIBLE TO RETURN VEHICLE AFTER 25-100 MILES TO HAVE ALL LUG NUTS RETORQUED TO MANUFACTURERS SPECIFICATIONS.			
1	RSA			Your tire purchase comes with a Emergency Roadside Assistance membership. For details, see the back of this invoice.	0.00	0.00	0.00
1	B2G2			BUY 2 GET 2 DISCOUNT	(182.00)	0.00	(182.00)
1	KMCC			CALL CENTER - KARL M.	0.00	0.00	0.00
1	APC				0.00	0.00	0.00
				Free Air Pressure Check			

SEE NEXT PAGE

EVANS TIRE & SERVICE CENTERS

Evans Tire & Service Centers
 330 N. El Camino Real
 Encinitas, CA 92024
 (760)942-2162

FREE OIL CHANGES / EXCLUSIVE DISCOUNTS & SPECIALS
 Text EVANSTIRE to 833-669-0337

Customer ID: 3114067691
 Name: JOHN ELLISON
 Address: NA
 Address 2:
 City, State, Zip Code: ENCINITAS, CA, 92024
 Home Phone: (760) 535-1258
 Work Phone: () -
 Mobile Phone: () -
 Tax Exempt #:

Year: 94
 Make: ROLLS-ROYCE
 Model: SILVER SPIRIT II
 Lic No: 36653
 VIN: 1
 Color: WHITE
 Engine: 1
 Mileage In: 48686
 Mileage Out: 48686

Create Date: 01/13/22 13:26:29
 Date/Time: 01/18/22 13:32:06
 Workorder #: 409352
 Invoice #: 227897

Email Address: na
 PO Number:
 Fleet/Wholesale: N

EPA #: CAL000440225
 BAR #: ARD00292322

Salesperson: R. CHIRIKDJIAN

Qty.	Part #	RFR	Loc	Description	Parts	Labor	Total
1	CC			LF _____ RF _____ LR _____ LF _____ INST. 1/18 @ 8:30AM SEE ROGER			
Sub-total:					0.00	0.00	0.00
Sub-total:					296.12	96.00	392.12

*** Customer Wishes To Discard Old Parts ***

CREDIT CARD #: XXXX-XXXX-XXXX-2000
 APPROVAL # : 884032
 TICKET # :

APPLABEL: AMERICAN EXPRESS
 AID: A000000025010801
 TVR: 0800008000
 IAD: 06580103A0A000
 TSI: E800
 ARQC: E6E56C0F8F3667D0
 ARC: 00
 CVM: S

Thank you for your business. Please visit WWW.EVANSTIRE.COM for coupons and additional warranty information.

Our goal is a PERFECT 5/5 score. If we haven't earned that, please call Customer Service at 760-579-4470

PAY AMOUNT
 AMEX 421.26
 TECH: 005695-0.00 SHELTON

PARTS TOTAL 296.12
 SALES TAX 29.14
 LABOR TOTAL 96.00
 GRAND TOTAL 421.26