



34
 Springfield, MA 01104
 Phone: 413-785-1665 Fax: 413-785-0970
 BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

INVOICE

73669
 Org. Est. # 065270

INVOICE

Work Completed : 10/12/2018 Date: 10/12/2018

Greenwood, Jacqueline
 163 Harwood Road
 Waterbury, CT 06706
 Cell 203-232-3949

1976 Rolls-Royce - Corniche -
 Lic # : 44829 Odometer In : 32337
 Odometer Out : 32337
 VIN# : DRE24808

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Brake res. gasket, repro UR 13114R	2.00	16.80	33.60	Owner was told the vehicle has a fuel leak - Per repair shop on Cape.		nc
Brake res screen, repro UR 13113R	1.00	42.00	42.00	Owner was told the brakes were unsafe Replace trunk key.		nc nc
Brake tank filler UR 15542R	3.00	63.00	189.00	Check for over vehicle for service needs.		nc
Sight glass oring SPC 1958	2.00	6.14	12.28	Work on car the week of Oct 12 - Car started when towed in. Front brake circuit did not build pressure. Rear built pressure, but no reserve. Fuel began leaking from engine, had to shut down	15.00	1,785.00
Sight glass screw UR13121	4.00	16.48	65.92	- Traced fuel leak to split pipe under carburetors. Need to remove carbs and intake top		
Accumulator seal kit RH 2435R	2.00	64.18	128.36	- Identified failed pump for front brakes, need hoses and seals for rear		
Sphere Diaphragm Kit RH 2619R	2.00	78.00	156.00	- Began repair, work continues next week Hazardous waste recycling costs		4.90
hydraulic pump, repro 363	1.00	724.00	724.00			
reservoir to pump hoses (set of 2) suppl Shop Supplies	1.00	244.50	244.50			
			29.55			

Org. Estimate 0.00 Revisions 0.00 Current Estimate 0.00

Labor:	1,785.00
Parts:	1,625.21
HazMat:	4.90
SubTotal:	3,415.11
Tax:	101.58
Total:	3,516.69
Bal Due:	\$3,516.69

[Payments -]
 Vehicle Received: 10/11/2018

Customer Number : 7229

Thank you for choosing J E Robison Service. We hope all work performed exceeds your expectations for both quality and value. We are constantly striving to improve our customer service. Installed parts and electrical parts are non returnable. General repair labor is warranted 6 months. There is no warranty on adjustments. Maintenance parts are warranted 60 days. Non-maintenance parts are warranted 12 months/12,000 miles. Some parts have longer warranty - see your service advisor for details. Warranty work must be performed in our shop.

Signature _____ Date _____



347 Page Boulevard
 Springfield, MA. 01104
 Phone: 413-785-1665 Fax: 413-785-0970
 BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

INVOICE

73694
 Org. Est. # 065285

INVOICE

Ref #: *****

Date: 10/19/2018

Greenwood, Jacqueline
 163 Harwood Road
 Waterbury, CT 06706
 Cell 203-232-3949

1976 Rolls-Royce - Corniche -
 Lic #: 44829
 VIN#: DRE24808

Odometer In : 32337
 Odometer Out : 32337

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Climate control relay UD15493R Shop Supplies	1.00	78.45	78.45	Work completed through 10/19 - We repaired the fuel pipe disconnection (had looked like a break) under the intake. - Also found that the left carburetor float needle and seat fell apart because they were improperly installed. Once we correctly installed these parts, we got the engine running. - Identified that there is no hydraulic pressure at the circuit 1 distribution valve. The problem is either with the pump or brake accumulator. We recommend replacing the pump first and started that disassembly. - Removed a burnt climate control relay and ordered a replacement. - Determined that the speedometer is inoperable and needs a new head - removed for repair. - Amp gauge fluctuates erratically although the voltage at the battery remains steady at 13.9 volts. - Clock is inoperable. - Right rear window is inoperable - may be a defective switch or motor. - Bled the #2 brake hydraulic system but found that circuit 1 has no pressure. - Adjusted the carburetors.	17.50	2,082.50
			3.92			
				Shipping		36.00
				Hazardous waste recycling costs		4.90

Org. Estimate 2,210.92 Revisions 0.00 Current Estimate 2,210.92

Labor:	2,082.50
Parts:	82.37
Sublet:	36.00
HazMat:	4.90
SubTotal:	2,205.77
Tax:	5.15
Total:	2,210.92
Bal Due:	\$2,210.92

[Payments -]

Vehicle Received: 10/19/2018

Customer Number : 7229

Thank you for choosing J E Robison Service. We hope all work performed exceeds your expectations for both quality and value. We are constantly striving to improve our customer service. Installed parts and electrical parts are non returnable. General repair labor is warranted 5 months. There is no warranty on adjustments. Maintenance parts are warranted 60 days. Non-maintenance parts are warranted 12 months/12,000 miles. Some parts have longer warranty - see your service advisor for details. Warranty work must be performed in our shop.

Signature _____ Date _____



347 Page Boulevard
 Springfield, MA. 01104
 Phone: 413-785-1665 Fax: 413-785-0970
 BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

INVOICE

73713

Org. Est. # 065313

INVOICE

Ref #: *****

Date: 10/25/2018

Greenwood, Jacqueline
 163 Harwood Road
 Waterbury, CT 06706
 Cell 203-232-3949

1976 Rolls-Royce - Corniche -
 Lic #: 44829
 VIN#: DRE24808

Odometer In : 32337
 Odometer Out : 32337

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
HYD. tank baffle UR18401	1.00	41.79	41.79	Work on car week of Oct 25 Dismantled reservoir, which was filled above the screens with sludge. This had ruined the pumps. Removed trays and shield, and found sludge. Cleaned that up and fitted new screens. Removed accumulators and valves, and pulled apart more of the system to clean out sludge. Work continues next week Shipping on parts Hazardous waste recycling costs	16.00	1,904.00
Brake pump kit RH 2438R	2.00	34.00	68.00			
Inlet Oring UE 35616	2.00	2.50	5.00			
Accum. Return hose UR14201R	1.00	24.00	24.00			
RH Accum return hose UR20144R	1.00	47.00	47.00			
Shop Supplies			9.29			

Org. Estimate 1,904.00 Revisions 0.00 Current Estimate 1,904.00

Labor:	1,904.00
Parts:	195.08
Sublet:	33.02
HazMat:	4.90
SubTotal:	2,137.00
Tax:	12.19
Total:	2,149.19
Bal Due:	\$2,149.19

[Payments -]
 Vehicle Received: 10/25/2018

Customer Number : 7229

Thank you for choosing J E Robison Service. We hope all work performed exceeds your expectations for both quality and value. We are constantly striving to improve our customer service. Installed parts and electrical parts are non returnable. General repair labor is warranted 6 months. There is no warranty on adjustments. Maintenance parts are warranted 60 days. Non-maintenance parts are warranted 12 months/12,000 miles. Some parts have longer warranty - see your service advisor for details. Warranty work must be performed in our shop.

Signature _____ Date _____



347 Page Boulevard
 Springfield, MA. 01104
 Phone: 413-785-1665 Fax: 413-785-0970
 BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

INVOICE

73716

Org. Est. # 065322

INVOICE

Ref # : *****

Date: 11/02/2018

Greenwood, Jacqueline
 163 Harwood Road
 Waterbury, CT 06706
 Cell 203-232-3949

1976 Rolls-Royce - Corniche -
 Lic # : 44829
 VIN# : DRE24808

Odometer In : 32345
 Odometer Out : 32345

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Accum. seal kit RH2435R	1.00	59.98	59.98	Shipping on parts		43.22
Sphere Diaphragm kit RH2619R	1.00	59.00	59.00	Gas		35.00
relay misc	3.00	22.11	66.33	Continue work week of Nov 1	19.00	2,261.00
Brake hydraulic fluid, pre-1980 Rolls & Bentley RR363	3.00	50.01	150.03	Hydraulic reservoir is all clean and set. Both pumps are clean, sealed, working. We had billed one pump but did not need the whole thing; part returned look for credit on next work order. Cleaned sludge and rebuilt one accumulator. The other was good and did not need repair. Flushed fluid through system to all wheel corners, working well. Noted some vibration from brakes (a separate mechanical problem)		
solvent, part cleaning G8909107 CRC	3.00	3.29	9.87	- Speedo did not work, odometer recorded miles. Removed speedo and sent for repair		
Shop Supplies			17.26	- Traced gas gauge problem, ordered sender at tank		
				- Noted torn compliance mounts when doing brake work - ordered mounts		
				- Stop lamp warning flashes - working on diagnosis		
				- Began work on windows - Mr. Greenwood noted those		
				- Replaced three burnt climate control relays, will test next week		
				Hazardous waste recycling costs		4.90

Org. Estimate 2,729.24 Revisions 0.00 Current Estimate 2,729.24

Labor:	2,261.00
Parts:	362.47
Sublet:	78.22
HazMat:	4.90
SubTotal:	2,706.59
Tax:	22.65
Total:	2,729.24
Bal Due:	\$2,729.24

[Payments -]
 Vehicle Received: 11/2/2018

Customer Number : 7229

Thank you for choosing J E Robison Service. We hope all work performed exceeds your expectations for both quality and value. We are constantly striving to improve our customer service. Installed parts and electrical parts are non returnable. General repair labor is warranted 6 months. There is no warranty on adjustments. Maintenance parts are warranted 60 days. Non-maintenance parts are warranted 12 months/12,000 miles. Some parts have longer warranty - see your service advisor for details. Warranty work must be performed in our shop.

Signature _____ Date _____



347 Page Boulevard
 Springfield, MA. 01104
 Phone: 413-785-1665 Fax: 413-785-0970
 BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

INVOICE

73754

Org. Est. # 065363

INVOICE

Ref #: *****

Date: 11/16/2018

Greenwood, Jacqueline
 163 Harwood Road
 Waterbury, CT 06706
 Cell 203-232-3949

1976 Rolls-Royce - Corniche -
 Lic #: 44829

Odometer In : 0

VIN# : DRE24808

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Air Hose UE 36871	1.00	218.81	218.81	Work on car week of Nov 16 - installed new right rear window motor and track pieces, including modifications to fit newer parts, - fabricated new air intake hose, old one broken. modified the part we can buy - identified and ordered compliance mounts - still investigating the charging problem, removed alternator and sent to auto electric people to evaluate. Exact replacement not available, - working on power seats - working on making front passenger window operate smoothly, - sent speedometer out for repair Speedo repair, includes shipping Shipping on parts Hazardous waste recycling costs	20.00	2,380.00
Window motor UD 71195R	1.00	395.00	395.00			
Window Coupling RH 9610R	1.00	39.44	39.44			
Washer XB 1077	1.00	6.30	6.30			
Foam washer UB 13667	1.00	3.30	3.30			
Comp mount UR 72000R	2.00	58.80	117.60			350.00
Shop Supplies			29.55			38.17
						4.90

Org. Estimate 3,633.70 Revisions 0.00 Current Estimate 3,633.70

Labor:	2,380.00
Parts:	810.00
Sublet:	388.17
HazMat:	4.90
SubTotal:	3,583.07
Tax:	50.63
Total:	3,633.70
Bal Due:	\$3,633.70

[Payments -]
 Vehicle Received: 11/16/2018

Customer Number : 7229

Thank you for choosing J E Robison Service. We hope all work performed exceeds your expectations for both quality and value. We are constantly striving to improve our customer service. Installed parts and electrical parts are non returnable. General repair labor is warranted 6 months. There is no warranty on adjustments. Maintenance parts are warranted 60 days. Non-maintenance parts are warranted 12 months/12,000 miles. Some parts have longer warranty - see your service advisor for details. Warranty work must be performed in our shop.

Signature _____ Date _____



347 Page Boulevard
 Springfield, MA. 01104
 Phone: 413-785-1665 Fax: 413-785-0970
 BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

INVOICE

73801

Org. Est. # 065412

INVOICE

Date: 11/26/2018

Greenwood, Jacqueline
 163 Harwood Road
 Waterbury, CT 06706
 Cell 203-232-3949

1976 Rolls-Royce - Corniche -
 Lic # : 44829
 VIN # : DRE24808

Odometer In : 32345
 Odometer Out : 32345

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Rebuilt CAV Alternator UE41719ASXMF	1.00	675.00	675.00	Work on car week of Nov 23 The alternator proved to be bad, which was why the amp gauge was jumping up and down. Looked at modifications to fit newer style, but ended up locating a correct original replacement, which we ordered and began to install. Also continued tracing other wiring faults in the dash	5.00	595.00
Voltage Regulator UD15154R	1.00	110.00	110.00			
Core charge on alternator, not repairable misc	1.00	350.00	350.00	Bench test alternator Found that the armature had shorted out and therefore the alternator cannot be rebuilt.		50.00
Shop Supplies			29.55			
				Shipping/handling on 365130		52.30
				Hazardous waste recycling costs		4.90

Org. Estimate 1,939.53 Revisions 0.00 Current Estimate 1,939.53

Labor:	595.00
Parts:	1,164.55
Sublet:	102.30
HazMat:	4.90
SubTotal:	1,866.75
Tax:	72.78
Total:	1,939.53
Bal Due:	\$1,939.53

[Payments -]
 Vehicle Received: 11/26/2018

Thank you for choosing J E Robison Service. We hope all work performed exceeds your expectations for both quality and value. We are constantly striving to improve our customer service. Installed parts and electrical parts are non returnable. General repair labor is warranted 6 months. There is no warranty on adjustments. Maintenance parts are warranted 60 days. Non-maintenance parts are warranted 12 months/12,000 miles. Some parts have longer warranty - see your service advisor for details. Warranty work must be performed in our shop.

Signature _____ Date _____

Customer Number : 7229



J E Robison Service Company, Inc.

347 Page Boulevard

Springfield, MA. 01104

Phone: 413-785-1665 Fax: 413-785-0970

BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

INVOICE ⁴

74027

Org. Est. # 065653

INVOICE

Date: 02/08/2019

Greenwood, Jacqueline

163 Harwood Road

Waterbury, CT 06706

Cell 203-232-3949

1976 Rolls-Royce - Corniche -

Lic # : 44829

VIN# : DRE24808

Odometer In : 32352

Odometer Out : 32352

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Anti-Freeze, Prestone	1.00	22.40	22.40	Work completed through 2/6.	6.00	714.00
AF				We fitted a new fuel sending unit and removed and replaced the thermostat. The safety plugs had melted out of the thermostat, which is a sign the car may have overheating problems in hot weather. Need to look at that when it's warmer. The thermostat part is done. The fuel gauge is working now. Work will continue when upholstery pieces are done		
Shop Supplies			1.12			
				Gas		25.00
				Hazardous waste recycling costs		4.48

Org. Estimate 25.00 Revisions 0.00 Current Estimate 25.00

Labor:	714.00
Parts:	23.52
Sublet:	25.00
HazMat:	4.48
SubTotal:	767.00
Tax:	1.47
Total:	768.47
Bal Due:	\$768.47

[Payments -]

Vehicle Received: 2/7/2019

Customer Number : 7229

Thank you for choosing J E Robison Service. We hope all work performed exceeds your expectations for both quality and value. We are constantly striving to improve our customer service. Installed parts and electrical parts are non returnable. General repair labor is warranted 6 months. There is no warranty on adjustments. Maintenance parts are warranted 60 days. Non-maintenance parts are warranted 12 months/12,000 miles. Some parts have longer warranty - see your service advisor for details. Warranty work must be performed in our shop.

Signature _____ Date _____

Visit us on the web : www.robisonservice.com

Service Advisor : White, Maribeth, Tech : Orlich, Bud 1; Turner, Alex



347 Page Boulevard
 Springfield, MA. 01104
 Phone: 413-785-1665 Fax: 413-785-0970
 BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

5
INVOICE

73855

Org. Est. # 065433

INVOICE

Ref #: *****

Date: 12/07/2018

Greenwood, Jacqueline
 163 Harwood Road
 Waterbury, CT 06706
 Cell 203-232-3949

1976 Rolls-Royce - Corniche -
 Lic # : 44829
 VIN# : DRE24808

Odometer In : 32350
 Odometer Out : 32351

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
---------------------------	-----	------	-----	-------------------	-------	-----

				Continue work on car	14.00	1,666.00
				<ul style="list-style-type: none"> - The clock is now working but the set knob is broken. A new clock is \$400. Clock is set and working for now. - Amp meter is bypassed, charging system working correctly but there are still electrical issues, probably corroded grounds and junctions in the fuse box. All working for now. - Speedometer is working properly now - Compliance mounts have been replaced - Engine is running well, fuel leaks fixed and tune settings good - Trunk assembled (apart when car arrived) - Dash is assembled - Made new hold down and terminations for battery in truck * There is a shake from the tires - should balance before return. There is a slight shake from brakes, did not bother owner so we left is alone		

Org. Estimate 1,666.00 Revisions 0.00 Current Estimate 1,666.00

Labor:	1,666.00
Parts:	0.00
SubTotal:	1,666.00
Tax:	0.00
Total:	1,666.00
Bal Due:	\$1,666.00

[Payments -]

Vehicle Received:

Customer Number : 7229

Thank you for choosing J E Robison Service. We hope all work performed exceeds your expectations for both quality and value. We are constantly striving to improve our customer service. Installed parts and electrical parts are non returnable. General repair labor is warranted 6 months. There is no warranty on adjustments. Maintenance parts are warranted 60 days. Non-maintenance parts are warranted 12 months/12,000 miles. Some parts have longer warranty - see your service advisor for details. Warranty work must be performed in our shop.

Signature _____ Date _____



J E Robison Service Company, Inc.

347 Page Boulevard
Springfield, MA. 01104

Phone: 413-785-1665 Fax: 413-785-0970

BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

INVOICE ⁶

73892

Org. Est. # 065509

INVOICE

Date: 02/01/2019

Greenwood, Jacqueline
163 Harwood Road
Waterbury, CT 06706
Cell 203-232-3949

1976 Rolls-Royce - Corniche -
Lic # : 44829
VIN# : DRE24808

Odometer In : 32352
Odometer Out : 32352

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
Sending unit, via trunk UR 13591R	1.00	233.41	233.41	Find out why engine won't warm up - start with new thermostat	0.50	59.50
Thermostat, Fail-safe UE 36600	1.00	127.32	127.32	Verified gauge is OK - engine not coming up to temp. Thermostat appears to have melted safety plugs. MAY need radiator, but t-stat is first to address. Parts are on order		
Thermostat gasket UE 73635R	1.00	10.80	10.80	Repair fuel gauge Trace wiring faults and order parts.	2.10	249.90
Sender gasket UE 73618R Shop Supplies	1.00	5.01	5.01	Check no start Car had spark and no fuel. Pump was not working when parked outside on 0 degree day. Pump worked when car warmed up. Note made but no repair needed for now	0.50	59.50
			18.83	Reupholster and rebuilt front seats (deposit) Advance billing for hides and trimming necessary to cover seats. Expect total costs in \$5,400 range per phone report 1/27		1,000.00
				Shipping		25.02
				Gas - car was empty		15.00
				Hazardous waste recycling costs		4.90

Org. Estimate 1,810.10 Revisions 0.00 Current Estimate 1,810.10

Labor:	368.90
Parts:	395.37
Sublet:	1,040.02
HazMat:	4.90
SubTotal:	1,809.19
Tax:	24.71
Total:	1,833.90
Bal Due:	\$1,833.90

[Payments -]
Vehicle Received: 2/1/2019

Customer Number : 7229

Thank you for choosing J E Robison Service. We hope all work performed exceeds your expectations for both quality and value. We are constantly striving to improve our customer service. Installed parts and electrical parts are non returnable. General repair labor is warranted 6 months. There is no warranty on adjustments. Maintenance parts are warranted 60 days. Non-maintenance parts are warranted 12 months/12,000 miles. Some parts have longer warranty - see your service advisor for details. Warranty work must be performed in our shop.

Signature _____ Date _____

Visit us on the web : www.robison-service.com

**J E Robison Service Company, Inc.**347 Page Boulevard
Springfield, MA. 01104

Phone: 413-785-1665 Fax: 413-785-0970

BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

INVOICE**74169**

Org. Est. # 065678

INVOICE

Work Completed : 03/29/2019

Date: 03/29/2019

Greenwood, Jacqueline
163 Harwood Road
Waterbury, CT 06706
Cell 203-232-3949

1976 Rolls-Royce - Corniche -

Lic # : 44829

Odometer In : 32352

Odometer Out : 32352

VIN # : DRE24808

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
---------------------------	-----	------	-----	-------------------	-------	-----

Remove front seats for re-upholstering
Completed.

2.00 238.00

Re-upholster and rebuild front seats

4,400.00

Shipping

60.00

Org. Estimate 4,698.00 Revisions 0.00 Current Estimate 4,698.00

Labor:	238.00
Parts:	0.00
Sublet:	4,460.00
SubTotal:	4,698.00
Tax:	0.00
Total:	4,698.00
Bal Due:	\$4,698.00

[Payments -]

Vehicle Received: 3/29/2019

Customer Number : 7229

Thank you for choosing J E Robison Service. We hope all work performed exceeds your expectations for both quality and value. We are constantly striving to improve our customer service. Installed parts and electrical parts are non returnable. General repair labor is warranted 6 months. There is no warranty on adjustments. Maintenance parts are warranted 60 days. Non-maintenance parts are warranted 12 months/12,000 miles. Some parts have longer warranty - see your service advisor for details. Warranty work must be performed in our shop.

Signature _____ Date _____

Visit us on the web : www.robisonservice.com

Service Advisor : White, Maribeth, Tech : Orlich, Bud 1



J E Robison Service Company, Inc.

347 Page Boulevard
Springfield, MA. 01104
Phone: 413-785-1665 Fax: 413-785-0970
BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

INVOICE

74191

Org. Est. # 065834

Invoice from History

Work Completed : 04/05/2019 Date: 04/12/2019

Greenwood, Jacqueline
163 Harwood Road
Waterbury, CT 06706
Cell 203-232-3949

1976 Rolls-Royce - Corniche -
Lic # : 44829
VIN # : DRE24808

Odometer In : 33255
Odometer Out : 33255

Part Description	I Number	Qty	Sale	Ext	Labor Description	Hours	Ext
------------------	----------	-----	------	-----	-------------------	-------	-----

wire harness repair materials		1.00	12.88	12.88	Work completed through 4/5 - When we refitted the reupholstered seats we turned to the pre-existing wiring problems. The right seat had some broken wires underneath and we traced and fixed them. - The driver seat did not move fore and aft as it should. Traced this to broken wires in the harness through the doors (see report and photo Apr 12). Waiting for owner decision to remove door and fix this. - Replaced thermostat (part ordered previously) and ran car - warmup is correct now. - Adjusted engine running for spring.	10.20	1,213.80
misc							
Anti-Freeze, Prestone		1.00	22.40	22.40			
AF							

Org. Estimate 357.00 Revisions 0.00 Current Estimate 357.00

Labor:	1,213.80
Parts:	35.28
SubTotal:	1,249.08
Tax:	2.21
Total:	1,251.29
Bal Due:	\$0.00

[Payments - Visa - \$1,251.29]
Vehicle Received: 4/5/2019

Customer Number : 7229

Thank you for choosing J E Robison Service. We hope all work performed exceeds your expectations for both quality and value. We are constantly striving to improve our customer service. Installed parts and electrical parts are non returnable. General repair labor is warranted 6 months. There is no warranty on adjustments. Maintenance parts are warranted 60 days. Non-maintenance parts are warranted 12 months/12,000 miles. Some parts have longer warranty - see your service advisor for details. Warranty work must be performed in our shop.

Signature _____ Date _____

Visit us on the web : www.robisonservice.com



J E Robison Service Company, Inc.

347 Page Boulevard
 Springfield, MA. 01104
 Phone: 413-785-1665 Fax: 413-785-0970
 BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

INVOICE

74218

Org. Est. # 065886

INVOICE

Work Completed : 05/09/2019

Date: 05/10/2019

Greenwood, Jacqueline
 163 Harwood Road
 Waterbury, CT 06706
 Cell 203-232-3949

1976 Rolls-Royce - Corniche -
 Lic # : 44829
 VIN# : DRE24808

Odometer In : 33260
 Odometer Out : 33260

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
wire harness repair kit misc	1.00	33.12	33.12	Remove door to fix broken wires in the harness.		nc
Spar Plug, Champions -405- RN14YC	8.00	6.45	51.60	Traced and repaired breakage in a dozen wires in the door-body harness		
Brake hydraulic fluid, pre-1980 Rolls & Bentley RR363	3.00	55.01	165.03	Performed service for spring - Oil is done - Hydraulics are bled - AC is working - Replaced plugs and set tuning		nc
Interstate Battery, 800CCA. 1000CA. MTP24	1.00	168.95	168.95	Repaired driver door latch - key now works in left door Also made duplicate key		nc
Oil filter, Rolls Royce RH10003	1.00	49.98	49.98	Road test - car drives ok Noted some driveline vibration, not a concern to owner. This is a trait of the Detroit style axles in this car		nc
oil filter kit RR	1.00	43.12	43.12	Replaced battery, would not hold charge Done		nc
Washer, Drain plug XB1093	1.00	5.25	5.25	Labor for above	19.50	2,320.50
valvoline VR1 Racing 50W Val 235	10.00	10.98	109.80	This ended up being a little less time that we predicted The parts credits on this work order are for items billed on earlier work orders but not used		
Windshield washer solvent WASH	1.00	3.73	3.73	Gas		65.20
solvent, part cleaning G8909107 CRC	1.00	3.29	3.29	Key copy		12.63
HHS2000 synthetic spray lubricant HHS	1.00	8.50	8.50			
Accumulator seal kit RH 2435R	-2.00	64.18	-128.36			
Sphere Diaphragm Kit RH 2619R	-2.00	78.00	-156.00			
hydraulic pump, repro 363	-1.00	724.00	-724.00			
reservoir to pump hoses (set of 2) suppl	-1.00	244.50	-244.50			

Visit us on the web : www.robison-service.com

Service Advisor : White, Maribeth, Tech : Orlich, Bud 1; Turner, Alex



J E Robison Service Company, Inc.

347 Page Boulevard
Springfield, MA 01104
Phone: 413-785-1665 Fax: 413-785-0970
BMW, Jaguar, Mercedes, Land Rover, Rolls/Bentley specialists

INVOICE

74218

Org. Est. # 065886

INVOICE

Work Completed : 05/09/2019 Date: 05/10/2019

Greenwood, Jacqueline
163 Harwood Road
Waterbury, CT 06706
Cell 203-232-3949

1976 Rolls-Royce - Corniche -
Lic # : 44829
VIN# : DRE24808

Odometer In : 33260
Odometer Out : 33260

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext
---------------------------	-----	------	-----	-------------------	-------	-----

Org. Estimate 1,333.18 Revisions 0.00 Current Estimate 1,333.18

Labor:	2,320.50
Parts:	-610.49
Sublet:	77.83
SubTotal:	1,787.84
Tax:	-38.16
Total:	1,749.68
Bal Due:	\$1,749.68

[Payments -]
Vehicle Received: 5/9/2019

Customer Number : 7229

Thank you for choosing J E Robison Service. We hope all work performed exceeds your expectations for both quality and value. We are constantly striving to improve our customer service. Installed parts and electrical parts are non returnable. General repair labor is warranted 6 months. There is no warranty on adjustments. Maintenance parts are warranted 60 days. Non-maintenance parts are warranted 12 months/12,000 miles. Some parts have longer warranty - see your service advisor for details. Warranty work must be performed in our shop.

Signature _____ Date _____

Visit us on the web : www.robisonservice.com