

Repair Order Detail - Internal Copy

RO Number: 84199

RO Status: READY TO POST

Customer: GERSTENHABER, DAVID

[Click to View Cust Copy](#)

Phone(s): Contact: (917)520-8491

Main: (917)520-8491

Cell: (917)520-8491

Vehicle: SCBLE37G45CX19344

2005 ARNG

BLACK

Mileage: 45,993

Payment type: CASH

Waiter: No

Service advisor: 12

Promised time: 05:00 PM

Estimate: 0.00

Tag number: T6542

Promised date: 12/02/2022

Customer Comments: No

~~~~~  
A CLIENT STATES THAT THE CHECK ENGINE LIGHT IS ON DISPLAY  
88 CPB CHECK ENGINE LIGHT 1.00 269.00

Tech(s): 147

Pts: 0.00 Lbr: 269.00 Other: 0.00 Total Line A: 269.00

Story: 45993 scan system for check engine lite. found an error for secondary air system malfunction. checked system and seems okay. clear faults and road test car. no problem occurred at this time

~~~~~  
B CLIENT STATES THAT THE RIGHT FRONT WINDOW DOES
88 CPB WINDOW 1.00 269.00

Tech(s): 147

Pts: 0.00 Lbr: 269.00 Other: 0.00 Total Line B: 269.00

Story: 45993 checked RH. front window operation. car need new window regulator. part not available at this time

~~~~~  
C CLIENT STATES THAT THE ANTENNA IS INOP  
88 CPB ANTENNA 0.00 0.00

Tech(s): 147

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00

Story: 45993 removed left side trunk panel and checked for power and ground for the antenna. need new antenna. not available at this time.

~~~~~  
D INITIAL DIAGNOSTICS \$807
88 CPB DIAG 0.00 0.00

Tech(s): 147

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00

~~~~~  
E\*\* CLIENT REQUEST TO PERFORM ANNUAL SERVICING AS RECOMMENDED  
02 CPB ANNUAL SERVICE 8.00 2,152.00

Tech(s): 147

Pts: 0.00 Lbr: 2,152.00 Other: 0.00 Total Line E: 2,152.00

Story: 45993 changed oil and filter, flushed brake system, removed spark plugs cleaned them and reinstalled. don t need to be replaced.

~~~~~  
F** CONTINUE REPAIRS ON LINE B - WINDOW REGULATOR
88 CPB WINDOW 6.00 1,614.00

Tech(s): 147

PP61224PB 1 ASSY EWL FRT RH N/AM 2,343.48

Pts: 2,343.48 Lbr: 1,614.00 Other: 0.00 Total Line F: 3,957.48

Story: 45993 REMOVED RH. FRONT DOOR PANEL AND REPLACED DEFECTIVE WINDOW REGULATOR.

Repair Order Detail - Internal Copy

RO Number: 84199

RO Status: READY TO POST

Customer: GERSTENHABER,DAVID

[Click to View Cust Copy](#)

Phone(s): Contact: (917)520-8491

Main: (917)520-8491

Cell: (917)520-8491

Vehicle: SCBLE37G45CX19344

2005 ARNG

BLACK

Mileage: 45,993

Payment type: CASH

Waiter: No

Service advisor: 12

Promised time: 05:00 PM

Estimate: 0.00

Tag number: T6542

Promised date: 12/02/2022

Customer Comments: No

~~~~~				
G**	CLIENT REQUEST TO REPLACE BOTH BATTERIES			
60	CPB	BATTERY	2.50	672.50
	Tech(s): 147			
	000915105DE	1 BATTERY WITH CHARGE		328.00
		STATE INDI		
	000915105DC	1 BATTERY WITH CHARGE		289.77
		STATE INDI		
Pts:	617.77	Lbr:	672.50	Other:
				0.00
Total Line G:				1,290.27
Story: 45993 REPLACED BOTH BATTERIES.				
~~~~~				

Customer Pay	
Labor	4,976.50
Parts	2,961.25
Lube	0.00
Sublet	0.00
Miscellaneous/Shop Charge	0.00
Deductible	0.00
Total Charges	7,937.75
Less Insurance/Adjustment	0.00
Sales Tax	684.63
Total	8,622.38