#### Third Party Inspection Report For:



# VEHICLE INFORMATION VIN: J925612 Engine Size/Type: 429cdi V8 Transmission Type: Automatic Drive Type: Mileage: 39,576

# EVALUATION INFORMATION Evaluation Result: Complete Date: Dec 7, 2020 Inspector Name: Dealership: Classic Promenade

### **About Pre-Purchase Inspections**

This report has been compiled based on the results of the inspection performed by a qualified, specially trained inspector. The report demonstrates the condition of the vehicle based on a comprehensive visual inspection and road test of the vehicle at the time of the inspection.

The inspection report documents specific inspection points, a test drive & performance qualities, and dozens of condition photos of the exterior, interior, underhood, drivetrain, chassis and undercarriage of the vehicle.

#### Please Note:

Under most circumstances, the inspector will drive the vehicle in order to best determine the vehicle's handling and overall roadworthiness. However, in certain instances, the vehicle owner is reluctant to have persons other than themselves drive their vehicle, even though our inspectors are highly qualified to do so. In those cases the seller is requested to drive the vehicle following instructions provided by the inspector and the inspector will ride along and observe the vehicle characteristics during that test drive.

Also, our inspectors do not use tools and are not permitted to unseal, disassemble, or otherwise handle any hidden vehicle components. They can only document what they can observe in ambient light or with a flashlight.

Also, sellers will not generally allow any disassembly of the vehicle for testing or diagnosis. Therefore, our inspectors do not perform any disassembly of the vehicle for their testing purposes. In addition, because our inspections are mobile, there rarely are lifts available that would allow us unimpeded physical access underneath the vehicle. The inspection report was specifically designed to extract specific information from various systems and components through visual inspection techniques, vehicle performance characteristics and specific road testing observations.

#### Reminder:

Most classic vehicles are generally going to have, at a minimum, some type of minor defects. Some defects, and the degree of defect, are more subjective than objective. Subjectivity can sometimes result in slightly different opinions and observations.

The inspector cannot provide you with advice on whether to purchase or not purchase this vehicle.

The inspector makes no representations or warranties regarding its service in consideration of vehicle design, compliance with manufacturer specifications, operation, mechanical condition, safety, authenticity, provenance, title history, registration history, or market value of any vehicle inspected, or of any component parts.

#### **How To Use This Report**

#### **FOR BUYERS:**

In order to maximize the information and value this report provides, the inspector recommends using this report to:

- 1. Determine the accuracy of the owner's description and confirm their statements of condition.
- 2. Follow up with the vehicle owner regarding any new concerns raised from the inspection
- 3. Provide support during negotiations with the vehicle owner or for estimating vehicle repair costs.
- 4. Get a better idea of valuation when combined with further research to make a more informed decision.
- 5. Compare the condition of this vehicle to the condition of others like it that you are considering.

# **Inspection Report**

S - Satisfactory Year:
R - Repair Recommended Make:
N/A - Not Applicable Model:

		S	R	N/A	Notes
		<u> </u>	I N	IN/A	Exterior - Body
1	General Body Condition				No dents, no signs of rust. No Damage
	Body Modifications		-	111	None
	Body Panel Fit		╟	╢┝┷	
	Paint Condition		1	-	Overall very good. Older re-paint, some very minor cracking.
_	Rust/Corrosion			111	
	Door Condition		1	ĦŤ	
$\overline{}$	Door Weatherstripping				
	Door Handles/Locks		1	_	
	Front Fenders				
	Rear Fenders		1		
11	Hood Condition				
12	Roof/Pillars/Roof Rack			1	
13	Trunk/Hatchback	1		1	
14	Front Bumper	1	П		
15	Rear Bumper	V			
	Fuel Door Operation/Gas Cap	1			
17	Side Mirrors	V			
18	Truck Bed/Tailgate			V	
		S	R	N/A	Notes
				E×	terior - Glass/Trim
19	Front Windshield	V			
20	Rear Windshield	<b>V</b>			
21	Door Glass Condition	<b>V</b>			
22	Grill	<b>V</b>			
23	Body Trim/Moldings	<b>'</b>			
24	Chrome Condition	<b>'</b>			
25	Convertible Top			V	
	Wipers - Front/Rear	V	$\coprod$		
27	Antenna/Operation			Щ	
		S	R	N/A	
				E	exterior - Lighting
	Headlights	~	<b> </b>	<u> </u>	
	Fog Lights		╙	<i>\</i>	
	Side Marker Lights		<b> </b>	#	
	Tail Lights	~	╙	Ш	
	Turn Signals	<u> </u>	<b> </b>	#	
	Brake Lights/Center Light	<u> </u>	╙	<del>     </del>	
	Emergency Road Hazard Lights	<u> </u>		#	
35	Reverse Lights	<b>'</b>			

36	License Plate Lights	<b>V</b>				
37	Other Lights				~	
		S		R	N/A	Notes
					ln	terior - Condition
38	General Condition/Odors	7				No odors, overall fit and finish is very good
39	Interior Modifications				<b>'</b>	
40	Headliner	~				No rips, Does not sag.
41	Front Seat Covers	<b>V</b>				Good. Mild cracking.
42	Rear Seat Covers	<b>V</b>				
43	Seat Belts	<b>V</b>				
44	Headrests	<b>V</b>				
45	Front Carpet/Floor Mats	<b>V</b>	Ц	Щ	Ш	
46	Rear Carpet/Floor Mats	1				
	Cargo Carpet	<b>V</b>	Щ	Щ		
48	Door Sill Plates	<b>V</b>		4		
	Door Trim Panels	<u> </u>	L			Driver's door missing a light by the handle.
	Door Glass/Tint	<u> </u>		4		
	Dashboard	~	$\coprod$	_		No cracks or warping
	Interior Trim/Moldings	1		4		
	Airbag Covers	<u>                                     </u>		_	~	
	Glove Box Operation	Ш	Ľ	4		Does not fit complely square
_	Spare Tire	~	L	4		
	Tire/Jack/Tools	<u> </u>		4		
57	Toolkit Complete		Ш	Щ	~	
		S		R	N/A	Notes
				ln <sup>.</sup>	terior -	Convenience & Controls
	General Condition	~	┞			
	Owner's Manuals	<b>V</b>	⊬	$\dashv$	$\vdash$	
	Gearshift Operation	<b>V</b>	⊩		₩	
	Parking Brake Control	<b>V</b>	⊬		$\vdash$	
	Hood Release Tilt/Telescope Steering	~	⊩		$\blacksquare$	Works
	·	1	⊬	-	$\vdash$	VVOING
	Seat Position Adjusters Power Seat Switch/Motor	V	┞	$\dashv$	$\blacksquare$	
	Power Seat Switch/Motor  Power Window Switch/Motor	V	╁	┵	┢═┪	
	Door Locks/Power Switches	+	╟		┞┼┤	All work
	Power Mirrors	1	⊬	┥	$\vdash$	, at the state of
	Sunroof		╬		1	
	Sunvisor Vanity Mirrors		╟			
	Windshield Wiper Controls	1	╬	┽┦	┞	
	Defogger/Defogger Light	+	╟	┽┪	V	Heater does not work
	Horn	V	┞	-		
	Remote Fuel Door Release	V	┢	═╁	Н	
	Remote Trunk Release	1	╫	$\dashv$	┪	
	Cigarette Lighter	V	┢	═╣	Н	
	Remote Key Fob	V	╬	-	┰	
	Alarm	++	╫	-	1	
		S		R	N/A	Notes
						Instruments & Lighting
79	Gauges					

80	Odometer		Т	$\neg$				
	Dash/Instrument Lighting	1	╁	4				
	Check Engine Light	╟┷┥	╀┝	┥	V			
	Airbag Warning Light	╟─┤	╁┝	$\dashv$	V			
	ABS Warning Light	Н	11	┪	V			
	Clock		╽,	7		Does not work		
	Dome Light	1	₩	۲				
	Rear View Mirror/Compass		╁	1				
	Sunvisor Vanity Lights		┰	┪	П			
	Trunk Light			1				
	Warning Lights - Other	V	T	┪				
	3 3	S		R	N/A	Notes		
Interior - AC/Heat								
91	AC Operation/Temperature	1	П	┪		Blows cold		
	Heater Operation/Temperature	П	∙	7	П	Does not work		
	Climate Control Operation	1						
	Blower Speeds/Operation	1	$\top$	T	П			
	A/C Registers							
96	Seat Heater/Cooler Operation	П	⇈		V			
		S		R	N/A	Notes		
				lr	nterior -	Radio & Entertainment		
97	Radio Operation/Condition	V						
98	Speaker Operation/Condition	~						
99	CD/DVD Operation				~			
100	Navigation System				~			
	Back Up Camera				V			
102	Rear Entertainment System				~			
		S		R	N/A	Notes		
					Eng	ine & Under Hood		
	Engine/Underhood Modifications	~				No modificaitons		
$\blacksquare$	Hood Release Operation	~	╙	4				
	Hood Latch Operation	1	1	4				
	Hood Hinges/Struts	<b>V</b>		_				
	Hood Insulation	$\square$	۱	4		Starting to rip in a few places		
	Engine Emissions Placard	╟—	╨	4	<b>V</b>			
	Engine Emissions System		╀		<b>"</b>			
	Battery Condition/Battery Hold Down	V	╁	4				
	Alternator/Generator	<b>V</b>	╬	4				
$\blacksquare$	Engine Wiring	<b>V</b>	╫		┟├─┤	Llough drip looks of care this old		
	Engine Leaks		١	4	$\parallel \parallel \parallel$	Usual drip leaks of cars this old		
	Cooling System/Radiator/Cap Radiator Coolant Condition	V	╫	4				
	Heater Hoses - AC Hoses	V	╬	+				
-	Drive Belts Condition	V	╁┝	_				
	Drive Belts Condition  Air Cleaner/Filter	V	╬	+				
	Engine Oil Condition		110	$\dashv$		Next owner might want to change		
	Engine Oil Sludge	┞	╫	4	V	None owner might want to change		
	Transmission Fluid Condition	┟┝═┥	1 .	爿		Next owner might want to change		
	Power Steering System		₩,	-	$H \rightarrow$	Trock owner might want to change		
	Brake Master Cylinder Fluid Check	V	╫	$\dashv$				
123	Drake Masier Cylinaer Flaid Check							

124	Windshiled Washer Fluid	<b>V</b>	П			П	
		S	ľ	R	N/	/A	Notes
						Drive	etrain & Chassis
125	Chassis/Undercarriage Condition	1	П			П	
126	Chassis/Undercarriage Modifications		П		V	丌	
127	Frame/Unibody Condition	~	П				
128	Exhaust System	~	$\prod$			$\prod$	
129	Suspension System	~				$\prod$	
130	Shock Absorbers	<b>'</b>					
131	Steering Condition	<b>V</b>					
132	Transmission/Cooler Line Leaks	<b>'</b>	$\prod$				
133	Brakes	~					
134	Tire Condition and Tread Depth	~	$\prod$				
135	Wheel Condition	<b>V</b>	$\prod$				
136	Tire Data Map		$\coprod$		۷	1	
		S		R	N/	Ά	Notes
							Test Drive
137	Test Drive Length & Speed	~	Ц				
138	Cold/Hot Start Quality	<b>'</b>	Ц			$\perp \!\!\! \perp$	
139	Starter Function Quality	~	Ц				
140	Engine Idle Quality	<b>V</b>	Ц		L		
141	Engine Noise/Knocks/Rattles		Ц		۷	4	
142	Engine Smokes/Excessive Blowby		Ц		۷	<u> </u>	
143	Normal Engine Operating Temperature	1	Ц			Щ	
	Engine Acceleration/Power Check	~	Ц	_	L	4	
145	Exhaust Noise Level	~	Ц		L		
146	Transmission/Clutch Operation	~	Ц		L		
	Transmission Shift/Gears Operate Smoothly	~	Ц			$\bot$	
	Steering Wheel Centered	~	Ц	_	L	Щ	
	Steering System Operation	~	Щ			$\bot\!\!\!\!\bot$	
	Vehicle Alignment/Tracking Check	~	Ц		L	Щ	
	Road Vibration	Щ	$\coprod$		۷	_	
	Tire Noise	Щ	Ц		۷	4	
153	Suspension and Handling Quality	~	Ц			$\bot$	
154	Brake Operation	<b>V</b>	$\coprod$				
155	Parking Brake Operation	~					
156	Speedometer/Odometer Operation	~	$\prod$				
157	Wind Noise	~					
158	Squeaks/Rattles		$\prod$		V	4	

#### Final Thoughts:

Overall this is a very solid driver's quality. Won't win any major awards, but it will turn heads. Paint is pretty good, better than a 6-footer, but not perfect. Interrior is very nice considering its all orignal and preserved.

## **Tire Information**

Right Front Tire	Right Rear Tire
Manufacturer:	Manufacturer:
Size:	Size:
Tread Depth:	Tread Depth:
	Spare Tire  Manufacturer: Size: Tread Depth:
Left Front Tire	Left Rear Tire
Manufacturer:	Manufacturer:
Size:	Size:
Tread Depth:	Tread Depth: