Third Party Inspection Report For:



	VEHICLE INFORMAT	ION
VIN:	ZARBA5564H1052355	
Engine Size/Type:	2.0 Litre 4-cyclinder	
Transmission Type:	5-speed	
Drive Type:		
Mileage:	77,196	I

EVALUATION INFORMATION												
Evaluation Result:	Complete											
	Jan 13, 2021											
Inspector Name:												
Dealership:	Classic Promenade											

About Pre-Purchase Inspections

This report has been compiled based on the results of the inspection performed by a qualified, specially trained inspector. The report demonstrates the condition of the vehicle based on a comprehensive visual inspection and road test of the vehicle **at the time of the inspection**.

The inspection report documents specific inspection points, a test drive & performance qualities, and dozens of condition photos of the exterior, interior, underhood, drivetrain, chassis and undercarriage of the vehicle.

Please Note:

Under most circumstances, the inspector will drive the vehicle in order to best determine the vehicle's handling and overall roadworthiness. However, in certain instances, the vehicle owner is reluctant to have persons other than themselves drive their vehicle, even though our inspectors are highly qualified to do so. In those cases the seller is requested to drive the vehicle following instructions provided by the inspector and the inspector will ride along and observe the vehicle characteristics during that test drive.

Also, our inspectors do not use tools and are not permitted to unseal, disassemble, or otherwise handle any hidden vehicle components. They can only document what they can observe in ambient light or with a flashlight.

Also, sellers will not generally allow any disassembly of the vehicle for testing or diagnosis. Therefore, our inspectors do not perform any disassembly of the vehicle for their testing purposes. In addition, because our inspections are mobile, there rarely are lifts available that would allow us unimpeded physical access underneath the vehicle. The inspection report was specifically designed to extract specific information from various systems and components through visual inspection techniques, vehicle performance characteristics and specific road testing observations.

Reminder:

Most classic vehicles are generally going to have, at a minimum, some type of minor defects. Some defects, and the degree of defect, are more subjective than objective. Subjectivity can sometimes result in slightly different opinions and observations.

The inspector cannot provide you with advice on whether to purchase or not purchase this vehicle.

The inspector makes no representations or warranties regarding its service in consideration of vehicle design, compliance with manufacturer specifications, operation, mechanical condition, safety, authenticity, provenance, title history, registration history, or market value of any vehicle inspected, or of any component parts.

How To Use This Report

FOR BUYERS:

In order to maximize the information and value this report provides, the inspector recommends using this report to:

- 1. Determine the accuracy of the owner's description and confirm their statements of condition.
- 2. Follow up with the vehicle owner regarding any new concerns raised from the inspection
- 3. Provide support during negotiations with the vehicle owner or for estimating vehicle repair costs.
- 4. Get a better idea of valuation when combined with further research to make a more informed decision.
- 5. Compare the condition of this vehicle to the condition of others like it that you are considering.

Inspection Report

S - Satisfactory	Year:
R - Repair Recommended	Make:
N/A - Not Applicable	Model:

		S		R	Τ	N/A	Notes
							Exterior - Body
1	General Body Condition	~			Τ		No dents, no signs of rust. No Damage
2	Body Modifications		Π		Т	~	None
3	Body Panel Fit	~			Γ		
4	Paint Condition			~			Several paint chips on doors and front bumper (see notes below)
5	Rust/Corrosion					~	
6	Door Condition	~	Π				Doors appear to be repainted
7	Door Weatherstripping			~			Passenger door jamb is peeling
8	Door Handles/Locks	~					
9	Front Fenders	~					
10	Rear Fenders	~					
11	Hood Condition	~					
12	Roof/Pillars/Roof Rack	~	\square				
13	Trunk/Hatchback	~					
14	Front Bumper	~					
15	Rear Bumper			~			Minor oxidation on top trim peice of rear bumper
16	Fuel Door Operation/Gas Cap	~					
17	Side Mirrors	~					
18	Truck Bed/Tailgate					~	
		S		R		N/A	Notes
					_	Ex	terior - Glass/Trim
_	Front Windshield	~					Small rock chip on front windshield
	Rear Windshield	~			Ц		
	Door Glass Condition	~					
	Grill	~					
_	Body Trim/Moldings	~					
	Chrome Condition	~			Ц		
	Convertible Top						New fabric top. Hard top in good conidtion.
	Wipers - Front/Rear	~			Ц		
27	Antenna/Operation	~			Ļ		
		S		R		N/A	Notes
						E	Exterior - Lighting
	Headlights				+		
	Fog Lights				ļ	~	
	Side Marker Lights				H		
	Tail Lights	·			\downarrow		
	Turn Signals	~					
	Brake Lights/Center Light	~			ļ		
	Emergency Road Hazard Lights						
35	Reverse Lights	~					

36	License Plate Lights		~		Π		
37	Other Lights				Π	~	
			S	R		N/A	Notes
				<u> </u>		lr	iterior - Condition
38	General Condition/Odors		~		Т		No odors, overall fit and finish is very good
39	Interior Modifications					~	
40	Headliner		~				No rips, Does not sag.
41	Front Seat Covers		~				Good. Mild cracking.
42	Rear Seat Covers		~				
43	Seat Belts		~				
44	Headrests		~				
45	Front Carpet/Floor Mats		~				
46	Rear Carpet/Floor Mats		~				
47	Cargo Carpet		~				
	Door Sill Plates		2				
	Door Trim Panels	[2				
	Door Glass/Tint		~				
	Dashboard			~	1		2 mild cracks in center dash
52	Interior Trim/Moldings		~				
	Airbag Covers				Щ	~	
_	Glove Box Operation			~			
_	Spare Tire		~		1		
_	Tire/Jack/Tools		~				
57	Toolkit Complete				Ц	~	
			S	R		N/A	
					Inte	erior -	Convenience & Controls
	General Condition		~	<u> </u>			
	Owner's Manuals		~		4		
	Gearshift Operation		<u> </u>	-	╉╋		
	Parking Brake Control		<u>~</u>		╢		
	Hood Release		~	-			
	Tilt/Telescope Steering		_		┥┼	~	
	Seat Position Adjusters		~	-	┥╀		
_	Power Seat Switch/Motor				┽╁	~	
	Power Window Switch/Motor		~		╉╀		
	Door Locks/Power Switches			┢┝──	╢	v	
	Power Mirrors Sunroof			-	╉╄	V	
			~	┢┝╼╸	╉╁	~	
	Sunvisor Vanity Mirrors Windshield Wiper Controls		<u>v</u>	-	╉╋		
	Windshield Wiper Controls Defogger/Defogger Light		~	┢┢━━	╉╋		
	Horn		~	-	╉╀		
_	norn Remote Fuel Door Release		-	┢┝──	╉╁	~	
	Remote Trunk Release		~	┝──	╉╋	-	
	Cigarette Lighter		~	┢┝━	╉╂		
	Remote Key Fob		<u> </u>	-	╉╋	~	
	Alarm			┢	╂	V V	
-70			S	R	┦	N/A	Notes
			5	T.	- ما		- Instruments & Lighting
70	Gauges			V			Tach does not go above 3k RPM (not calibrated) and fuel guage bobs.
15							

80	Odometer				-11		
				┢┝╾		⊢	
	Dash/Instrument Lighting	┞┝	4	┞┝╸	╺┽╀		
	Check Engine Light Airbag Warning Light	┼┝	-	┢┝━	┥╢	v	
	Airbag Warning Light ABS Warning Light	╀┝╸	┥	┢┝━	┥┦	v	
	Clock		┢	┢┝─		~	
				┢┝╾	-#	┝	
	Dome Light			┢┝━		┢─	
	Rear View Mirror/Compass			┝┝╾	-#	÷	
	Sunvisor Vanity Lights	╆┝╴		┢┝╾	-11	H	
	Trunk Light		4		-#	-	
90	Warning Lights - Other				_4		
			S	F	२	N/A	
01			_				Interior - AC/Heat
	AC Operation/Temperature	╀┝╴	_		-#		
	Heater Operation/Temperature		4	┟┝━	┥╢	⊢	
	Climate Control Operation	ŦÞ	4	┡┝	┩	⊢	
	Blower Speeds/Operation	╨┝	4	┟┝━	┥╢	╞	
	A/C Registers	╀┝╸	4	┞┝	┩		
96	Seat Heater/Cooler Operation						
			S	F		N/A	
07					ln	terior	- Radio & Entertainment
	Radio Operation/Condition	t Hei	4	╟┝╸	-11	-	
	Speaker Operation/Condition	11-	4	╘┝─			
	CD/DVD Operation	╀┝╸	-	┝┝╾	-#		
	Navigation System	╨╴	_	┢┝╾	-11	~	
	Back Up Camera	╟╴	_		-#	<u>/</u>	
102	Rear Entertainment System	╨┶				/	
		<u> </u>	S	F	۲ ۲	N/A	
107						Er	igine & Under Hood No modificaitons
	Engine/Underhood Modifications	++	_	╟┝─	-11	┝─	
	Hood Release Operation		4	┢┝─			
	Hood Latch Operation	t be		╟┝╸	-88	÷	
	Hood Hinges/Struts	┼┞	4	┟┝━	┥╢		Starting to rin in a few places
	Hood Insulation	╀┝		╟┝━	┥┦	~	Starting to rip in a few places
	Engine Emissions Placard	╨┝	4	┟┝━	┥╢		
	Engine Emissions System	╀┝	┢	╟┝━	┥┦	-	
	Battery Condition/Battery Hold Down Alternator/Generator			╟┝╸	┥╢	┝	
			$ \rightarrow $	╟┝━	╺┦┦	┝	
	Engine Wiring	┼┝	4	-	╢	┢	Usual drip leaks of cars this old
_	Engine Leaks	╀┝╴		╟┙	┥┦	┝	
	Cooling System/Radiator/Cap			┟┢━	┥╢	⊢	
	Radiator Coolant Condition	╀┠┛	4	╟┝╸	┥┦	<u> </u>	
	Heater Hoses - AC Hoses	┼┝		┟┝━	┥╢	~	
	Drive Belts Condition	μĻ	4	╟┝━	┥┦		
	Air Cleaner/Filter	┼┝		╞┝	╢	~	Novt owner might went to shares
	Engine Oil Condition	╀┝	-	 	4		Next owner might want to change
	Engine Oil Sludge	┼┝	┥	╟┝━	┥	~	Novt owner might went to shares
_	Transmission Fluid Condition	╀┝╸	┦	 	4	-	Next owner might want to change
	Power Steering System	╆┾╴		╟┝╸	┥┤	┢	
123	Brake Master Cylinder Fluid Check						

124	Windshiled Washer Fluid	/	Π		ΤΓ		
		S		R	N	J∕A	Notes
					<u> </u>	Dri	vetrain & Chassis
125	Chassis/Undercarriage Condition	~			Π		
126	Chassis/Undercarriage Modifications		Π		Π	~	
127	Frame/Unibody Condition	~	Π				
128	Exhaust System	~	Π		Π		
129	Suspension System	~					
130	Shock Absorbers	~	Π				
131	Steering Condition	~					
132	Transmission/Cooler Line Leaks	>	\prod				
133	Brakes	~					
134	Tire Condition and Tread Depth	~	\prod				
135	Wheel Condition	~					
136	Tire Data Map				l	~	
		S		R	N	J∕A	Notes
		_					Test Drive
137	Test Drive Length & Speed	~					
138	Cold/Hot Start Quality	~					
139	Starter Function Quality	~					
140	Engine Idle Quality	~					
141	Engine Noise/Knocks/Rattles					~	
142	Engine Smokes/Excessive Blowby					~	
143	Normal Engine Operating Temperature	~					
144	Engine Acceleration/Power Check	~	Ш				
145	Exhaust Noise Level	~					
146	Transmission/Clutch Operation	~					
147	Transmission Shift/Gears Operate Smoothly	~					
	Steering Wheel Centered	~	Ц		Ľ		
149	Steering System Operation	~					
150	Vehicle Alignment/Tracking Check	~	Ц		ĽL		
151	Road Vibration					<u>~</u>	
	Tire Noise		Ц		ĽĽ	~	
_	Suspension and Handling Quality	~					
154	Brake Operation	~					
155	Parking Brake Operation	~					
	Speedometer/Odometer Operation	~	Ц				
	Wind Noise	~					
158	Squeaks/Rattles			~			

Final Thoughts:

Paint chips near drivers door handle, 4 or 5 small chips on front bumper. Slight paint color difference on passenger door (possible repaint).

Overall this is a nice, fun to drive, and well cared for Alfa. The minor cosmetic imperfections are unoffensive, the leater is in fantasic shape, and the driving expereince is engaged. Our impressions of this car are good.

Tire Information

