

2016

Class 114

C

Silver Shadow, Bentley T

<u>Current Odometer Reading</u> <i>W 22732</i>	<u>Chassis Number</u> LRB15056
<u>Prior Odometer Reading & Year</u> 22123 2013	<u>Member's Name & Cell #</u> Curzon, Simon 816-785-9656
Mileage Driven to Meet: 602	<input type="checkbox"/> Check Here if Fire Extinguisher is Present <input checked="" type="checkbox"/>
Team Captain's Comments	
Coachwork Award Eligible	

Car in Motion Test (Optional)

	Max Deduction	Actual Deduction
Drive Train (Noise, Rattles, Smoothness)	4	
Brakes (Effectiveness)	4	
Road Performance (Power Pick Up)	4	
After Run Test (Idle, Overheating, Leaks)	4	
Total		

	Class Points	Senior Points	Coachwork Points
Maximum Available	400	100	
Minus Deductions	<i>(6)</i>	<i>()</i>	Interior
Total Points	<i>394</i>	<i>98</i>	Exterior
Plus Class Points		<i>492</i>	
Total Points			

[A] To be eligible for a Class Award, Car must earn a minimum of ...1st Place 360 points, 2nd Place 320 and 3rd Place 280 points

[B] The Score total from the Body & Interior sections of Class Judging will be added to the Total Class Judging Points to determine the Coachwork Awards. First two pages are used in Award Calculations.

[C] To be eligible for a Senior Award, Car must earn a minimum of 450 points. All cars eligible for Senior Awards will be scored in class competition and will be judged by the Senior Judging Team - using a Car in Motion Driving Test

INTERIOR

1

Owner Name: Curzon, Simon

Chassis Number: LRB15056

INSTRUMENTS & ACCESSORIES	Max Deduct	✓
IGNITION LIGHT AND OIL LIGHT:		
<i>*(Check without the engine running)</i>		
Non functioning oil light*	1	✓
Non functioning ignition light*	1	✓
INSTRUMENTS:		
<i>*(Check while cranking)</i>		
Non functioning warning light	1	✓
Non functioning turn signal lights	1	✓
Non functioning hi beam light	1	✓
Non functioning instrument light	1	✓
Non functioning map lights	1	✓
Non functioning roof lights	1	✓
Non functioning cigar lighter	1	✓
Non functioning oil pres or temp gauge	1	✓
Non functioning radio/tape deck	1	✓
Poorly fitted non standard equipment	1	✓
Non functioning clock	1	✓
ELECTRIC WINDOWS:		
Slow or noisy operation	1	✓
Non functioning	1	✓
INTERIOR LIGHTS:		
Non functioning interior light	1	✓
Non functioning door switch	1	✓
REMOTE MIRRORS:		
Non functioning mirror	1	✓
POWER DOOR LOCKS:		
Non Functioning power door lock	1	✓
FUSE BOX:		
Dirty	1	✓
Incorrect or missing fuse	1	✓
Incorrect relay or cut out	1	✓
Non functioning light	1	✓
Cracked or broken thermistor cover	1	✓
Non standard wiring to fuses	1	✓
BRAKE PEDAL RUBBER:		
Worn or missing	1	✓
PARKING BRAKE PEDAL RUBBER:		
Worn or missing	1	✓
DIP SWITCH RUBBER COVER :		
Missing	1	✓
28		
TOTAL		

INTERIOR	Max Deduct	✓
HEADLINER		
Stained or dirty	1	✓
Sagging or torn	1	✓
PARCEL SHELF:		
Stained or dirty	1	✓
Non authentic material	1	✓
SEATS:		
Hard or stained surface	1	✓
Dirty in the pleats	1	✓
Cracked or torn	1	✓
Non authentic material	1	✓
DOOR PANELS		
Stained or dirty	2	✓
Scratched or shrunk	1	✓
Loose or missing clips	1	✓
Dirty or worn arm rest	1	✓
DOOR SEALS:		
Poor or flat	1	✓
Cut or missing	1	✓
Non authentic material	1	✓
BRIGHTWORK:		
Scratched or worn	1	✓
Loose sill cover plate	1	✓
Missing sill cover plate	1	✓
TREADPLATE:		
Scratched or worn	1	✓
Scratched or cut rubbers	1	✓
CARPETS:		
Dirty	1	✓
Holes, shrunk or poor fit	1	✓
Poor binding	1	✓
Non authentic material	1	✓
Foot pad - Holes or worn	1	✓
Foot pad - non authentic material	1	✓
STEERING WHEEL:		
Cracked or marked	1	✓
INTERIOR WOOD:		
Cracked or chipped	1	✓
Water damage to veneer	1	✓
Poor refinishing	1	✓
KNEE ROLL PADS:		
Poor or damaged	1	✓
SEAT BELTS:		
Poor condition	1	✓
Missing or nonfunctioning	1	✓
HEADRESTS:		
Missing	1	✓
Poor condition	1	✓
36		
TOTAL		

EXTERIOR

2

Owner Name: Curzon, Simon

Chassis Number: LRB15056

EXTERIOR

	Max Deduct		✓
PAINT CONDITION:			
Dead or dull	1		✓
Orange peel, poor finish	1		✓
Chip	1	1	✓
Scratch	1	1	✓
Worn paint	1		✓
Colour mismatch	1		✓
Stress cracks at leaded seams	1	1	✓

BODY:

Dings or dents	1		✓
----------------	---	--	---

STRIPING COACHLINE:

Tape	1		✓
Poor or missing areas	1		✓
Colour mismatch	1		✓
Incorrect pattern or number	1		✓
Missing from trim rings	1		✓

DOOR ALIGNMENT:

Poor	1		✓
------	---	--	---

DOOR GAPS:

Large or tight	1		✓
----------------	---	--	---

EVERFLEX / CONVERTIBLE TOP:

Poor appearance	1		✓
Tear	1		✓
Non authentic material	1		✓
Non functioning	1		✓
Tonneau cover missing	1		✓
Rear window scratched or opaque	1		✓

GLASS:

Windscreen cracked	1		✓
Stone chips	1		✓
Pitted	1		✓
Separation in corners	1		✓
Door window scratched	1		✓

BRIGHTWORK

	Max Deduct		✓
DOOR HANDLES:			
Worn	1		✓
Non functioning	1		✓

WINDOW FRAMES:

Worn	1		✓
Scratched	1		✓
Poor appearance	1		✓
Out of alignment	1		✓

BUMPER COVERS:

Worn	1		✓
Scratched	1		✓
Rubber facings worn	1		✓
Rubber ends twisted	1		✓
Rubber faded or cracked	1		✓

TRIM MOULDINGS:

Dented	1		✓
Bent or scratched	1		✓
Poorly fitted or anchored	1		✓

GRILL:

Poor appearance/dirty	1		✓
Scratched	1		✓
Pitted	1		✓
Dented	1		✓
Poorly fitted to body	1		✓
Incorrect hardware	1		✓
Poor or incorrect mascot	1		✓

HUB CAPS:

Scratched or dented	1		✓
Mismatched	1		✓
Incorrect type (too late, too early)	1		✓

WRAITH II TYPE/CORNICHE:

Badge discolored	1		✓
Embellishing ring loose	1		✓
Poor appearance	1		✓

MIRRORS EXTERIOR:

Poor or pitted finish	1		✓
Poor or stained silvering	1		✓

③ 26
TOTAL

29
TOTAL

ENGINE COMPARTMENT I

3

Owner Name: Curzon, Simon

Chassis Number: LRB15056

RADIATOR, BELTS, HOSES	Max Deduct		✓
LEAKS			
Hose or Radiator	1		✓
Water pump	1		✓
Incorrect Hoses	1		✓
Incorrect Clamps	2		✓
Heater Tap Missing or Inoperative	1		✓
Fan clutch Loose or Non Operational	1		✓
Incorrect or Poor Belts (low in grooves)	2		✓
Expansion Tank Leaking (poor cond.)	2		✓
Coolant Probes Disconnected or Missing	1		✓

RADIATOR CAP:			
Chipped or poor finish	1	1	✓

NON AUTHENTIC:			
Equipment	1		✓
Finish	1		✓

START & IDLE			
Hard Starting	1		✓
Rough Or High Idle	1		✓
Slow Or Unresponsive Pick Up	1		✓
Noisy Tappets	1		✓

EXHAUST MANIFOLD AND EGR MANIFOLD:			
Leaking	2		✓
Cracked	2		✓
Missing or incorrect nuts	1		✓

EGR VALVE:			
Non working valve	2		✓
Leaking pipe	1		✓
Non insulated pipe	1		✓
Equipment missing	1		✓

NON AUTHENTIC:			
Equipment	1		✓
Finish	1		✓

①

TOTAL 31

BRAKES HYDRAULICS	Max Deduct		✓
RESERVOIRS:			
Dirty	2		✓
Low fluid	1		✓
Leaks	1		✓
Missing cap seals	1		✓
HOSE, PUMPS, SUPPLY:			
Leaking	2		✓
Poor condition	1		✓
PUMPS:			
Noisy	2		✓
Leaking	1		✓

ACCUMULATOR AND VALVE BODIES:			
Leaking	1		✓
High pressure hoses leaking or chaffing	2		✓
Incorrect finish brake lines	1		✓

NON AUTHENTIC:			
Equipment	1		✓
Finish	1		✓

ENGINE ELECTRICAL			
DISTRIBUTOR CAP:			
Cracked or broken	1		✓
Incorrect color	1		✓
H T LEADS:			
Worn or poor	2		✓
Incorrect type mismatched	1		✓
Incorrectly routed, not held in anchors	1		✓

DISTRIBUTOR:			
Incorrect C D system	2		✓

COIL:			
Non authentic or poor finish	1		✓

ALTERNATOR & REGULATOR:			
Non authentic	1		✓

WIPER MOTOR:			
Non authentic or poor finish	2		✓

WASHERS:			
Incorrect pump or hose	2		✓

WIRING:			
Poor or incorrect insulation	2		✓
Corroded or incorrect wire connectors	2		✓

RELAYS:			
Non authentic or cover	2		✓

SPEED CONTROL:			
Non authentic	1		✓
cover (RH side)	1		✓

TOTAL 39

ENGINE COMPARTMENT II

4

Owner Name: Curzon, Simon

Chassis Number: LRB15056

STEERING PUMP

POWER STEERING PUMP

	Max Deduct	
Noisy	1	✓
Leaks or low fluid	1	✓
Incorrect hose on return line	1	✓
Incorrect high pressure hose	1	✓
Leaks at cooler (behind grill)	1	✓
Non authentic	1	✓
Poor finish	1	✓

AIR CONDITIONING

COMPRESSOR:

Noisy or incorrect type	1	✓
Missing or not attached fuse	1	✓

HOSES:

Poor condition	2	✓
Leaks oil showing at couplings	1	✓
Non authentic	2	✓

HIGH PRESSURE PIPES:

Bent or kinked	2	✓
Missing anchor clips	2	✓
Damaged or rounded unions	2	✓

BLOWER MOTORS:

Noisy	1	✓
Non functioning	2	✓

DUCTS:

Insulation torn or missing	2	✓
----------------------------	---	---

SCUTTLE AIR INTAKE

Foam filter missing or deteriorated	1	✓
-------------------------------------	---	---

NON AUTHENTIC:

Equipment	2	✓
Finish	1	✓

29
TOTAL

FUEL SYSTEM

CARBURETORS:

Leaks	1	✓
-------	---	---

HEAT RISER PIPES:

Poor condition	2	✓
Damaged fittings or kinked lines	1	✓

FLEX LINES:

Leaks	1	✓
Non authentic	2	✓

AIR INTAKE HOSE:

Split	2	✓
Non authentic	1	✓
Missing or non authentic clips	2	✓

AIR CLEANER:

Dirty	1	✓
Missing hot air pickup	1	✓
Non authentic finish	1	✓

ENGINE COMPARTMENT

ENGINE:

Dirty	1	✓
Rocker covers oil leaks	2	✓
Poor cork seal inside oil filler cap	1	✓
Low oil level on dip stick	1	✓
Ground straps missing or disconnected	1	✓
Non authentic finish	1	✓
Non authentic equipment	1	✓

BONNET LIGHT:

Non functioning	1	✓
Non authentic or missing	1	✓

BONNET INSULATION:

Missing	1	✓
Poor condition	1	✓
Buttons missing	2	✓
Non authentic material	1	✓

BONNET PINS:

Missing bonnet pin bump stop	1	✓
------------------------------	---	---

SPRING TOWERS:

Poor finish	2	✓
-------------	---	---

STRUT RUBBERS:

Worn or missing	2	✓
-----------------	---	---

35
TOTAL

UNDERSIDE AND SUB FRAMES

5

Owner Name: Curzon, Simon

Chassis Number: LRB15056

STEERING AND SUSPENSION

Max Deduct

✓

BALL JOINTS:

Torn or missing boots	2	✓
Grease nipples fitted	2	✓
Split pins missing	2	✓

TIE ROD ENDS:

Torn or missing boots	2	✓
Split pins missing	2	✓
Lock tabs missing at yokes	1	✓

STEERING IDLER:

Leaking	2	✓
---------	---	---

STEERING RACK OR BOX:

Leaks at spool valve	2	✓
Leaks at convoluted seals	1	✓

STEERING COLUMN:

Rusted universal joints	1	✓
Cracked or broken rubber coupling	2	✓
C.V Joint Cover Torn or Missing	2	✓
Missing Heat Shields	2	✓

UPPER CONTROL ARMS

Compliance mount torn	2	✓
-----------------------	---	---

LOWER CONTROL ARMS

Bushes worn	2	✓
-------------	---	---

NON AUTHENTIC:

Finish or dirty	1	✓
Equipment	2	✓

UNDERBODY

Rust or Corrosion on Floor Pans	2	✓
Damaged or Bent Floor Pans	2	✓
Damaged or Bent Subframes	2	✓
Damaged or Bent Jacking Points	2	✓
Dirty Areas	1	✓

POWER TRAIN

Engine Oil Leaks	2	✓
Transmission Fluid Leaks	2	✓
Dirty Sub Frames	2	✓
Diff. Carrier Mounts Torn or Broken	2	✓
Detroit Coupling Leaks or Split	2	✓
Differential Leaks	2	✓
Shock absorbers leaking	2	✓

53
TOTAL

BRAKES AND HYDRAULICS

Max Deduct

✓

Rusted Brake Lines	2	✓
Poor or Perished Brake Hoses	4	✓
Rusted Brake Cables	2	✓
Damaged Bleed Nipples	2	✓
Leaks, including Rat Trap	2	✓
Leaking Height Control Valve	2	✓
Leaking Rams	2	✓

FUEL SYSTEM

FUEL PUMP:

Noisy	1	✓
Leak	2	✓
Poor or damaged fittings	2	✓

FUEL LINE:

Leak	2	✓
Non authentic	2	✓
Poor or damaged fittings	2	✓
Non authentic finish	1	✓

FUEL FLEX HOSE:

Rusted or damaged	2	✓
Non authentic	1	✓

FUEL FILTER:

Leak	2	✓
Damaged	1	✓
Poor or damaged fittings	1	✓
Non authentic	2	✓

EXHAUST SYSTEM

Poor Condition	1	✓
No Catalytic Converters	2	✓
Bent or Missing Hangers	1	✓
Hitting Cross Member or Floor	1	✓
Missing Grass or Heat Shield	1	✓
Missing Polished Ends from Tail Pipe	1	✓
Leaks	2	✓
Non Authentic Finish	1	✓
Non Authentic Equipment	2	✓

49
TOTAL

S
H
H
C
H
H
S
H
S
A
O
R
H
H
H
H
H
H
H
O
H
H
H
A
H
H

BOOT, TYRES AND STANDING HEIGHT

6

0
1
2
3
4
5
6
7
8
9
A
B
C
D
E
F
G
H
I
J
K
L
M
N
O
P
Q
R
S
T
U
V
W
X
Y
Z

Owner Name: Curzon, Simon			
BOOT TOOLS AND LIGHTS			
LIGHTS (non working units):	Max Deduct		✓
Side lights and markers	1		✓
Headlamp low and high beams	1		✓
Tail lamps	1		✓
Brake lamps	1		✓
Reverse and license plate lights	1		✓
Indicators and hazard lights	1		✓
Cracked or broken lens	1		✓
TOOL KIT:			
Tool missing from kit	1	1	✓
Missing bulbs	1		✓
Missing owners manual	1		✓
LARGE TOOLS:			
Missing jack or wheel wrench	1		✓
BATTERY:			
Wrong size	1		✓
No hold down	1		✓
Incorrect hold down	1		✓
Terminals corroded	1		✓
Incorrect terminal or wiring	1		✓
Missing fly nut	1		✓
Dirty	1		✓
BATTERY COVER:			
Missing or cracked	1		✓
Poor condition	1		✓
Poor strap condition or missing	1		✓
GAS TANK DOOR EMERGENCY PULL:			
Missing ring	1		✓
Non working	1		✓
BOOT LIGHT:			
Non working	1		✓
Light missing	1		✓
25			
TOTAL			

Chassis Number: LRB15056			
BOOT INTERIOR			
BOOT LID SEAL:	Max Deduct		✓
Split or perished	1		✓
Seal missing	1		✓
Poor appearance	1		✓
CARPET:			
Incorrect carpet	1		✓
Holes or worn spots	1		✓
Missing carpet clips	1		✓
Water stains	1		✓
Side panels screws missing	1		✓
Incorrect screws	1		✓
BOOT LID:			
Out of adjustment (<i>hard to close</i>)	1		✓
Out of adjustment (<i>lid rattles</i>)	1		✓
Missing latch cover	1		✓
Poor or damaged hinge covers	1		✓
Sagging boot lid carpet	1		✓
TYRES			
Wrong Size or Mismatched Type	1		✓
Missing Valve Stem Cover	1		✓
Poor or Worn Tyre	1		✓
SPARE TYRE:			
Valve core positioned to floor access hole	1		✓
STANDING HEIGHT			
Rear Suspension Low	1		✓
No Action from Height Leveling	1		✓
20			
TOTAL			
Original Tyre Sizes:			
• 845 x 15 to chassis #13000			
• 205 x 15 to chassis #18269			
• HR70 15 to the end of series			
• Replacement for 845x15 & 205R 15 is *P215R 15			

2016

Class 114

C
Senior-003

Silver Shadow, Bentley T

<u>Current Odometer Reading</u> 22734	<u>Chassis Number</u> LRB15056
<u>Prior Odometer Reading & Year</u> 22123 2013	<u>Member's Name & Cell #</u> Curzon, Simon 816-785-9656
Mileage Driven to Meet: 602	<input type="checkbox"/> Check Here if Fire Extinguisher is Present
Team Captain's Comments	

Senior Score Sheet

Car in Motion Test (Optional)	Max Deduction	Actual Deduction
Drive Train (Noise, Rattles, Smoothness)	4	
Brakes (Effectiveness)	4	
Road Performance (Power Pick Up)	4	
After Run Test (Idle, Overheating, Leaks)	4	
	Total	

[A] To be eligible for a Class Award, Car must earn a minimum of ...1st Place 360 points, 2nd Place 320 and 3rd Place 280 points

[B] The Score total from the Body & Interior sections of Class Judging will be added to the Total Class Judging Points to determine the Coachwork Awards. First two pages are used in Award Calculations.

[C] To be eligible for a Senior Award, Car must earn a minimum of 450 points. All cars eligible for Senior Awards will be scored in class competition and will be judged by the Senior Judging Team - using a Car in Motion Driving Test

DRIVING TEST

1

Owner Name: Curzon, Simon

Chassis Number: LRB15056

ENGINE:

	Max Deduct	
Noisy	3	✓
Poor Performance / Misfire	5	✓
Smoke	3	✓
Leaks at "Check Stop"	2	✓

EXHAUST

Leaks	2	✓
Rattles or Knocks	2	✓

Scrub at under exhaust during stop check caused slight rattle which stopped normal wear for ageing

DRIVE LINE

CLUTCH:

Ineffective	2	✓
Shudder	2	✓

GEARBOX / TRANSMISSION:

Poor shift	3	✓
Noisy	2	✓

PROP-SHAFT:

Noisy universal joints	2	✓
------------------------	---	---

REAR END:

Noisy / whine	2	✓
Drive dog clunk	2	✓

WHEELS / TYRES:

Rumble or thump	3	✓
Spokes / hubcaps	3	✓

BRAKES

Pulling to One or Other Side	5	✓
Noisy / Clunks	2	✓
Squeal	2	✓
Ineffective	5	✓
Excessive Pedal Travel	2	✓

TOTAL

STEERING AND SUSPENSION

	Max Deduct	
Feedback	2	✓
Excessive Play	5	✓
Knocks	2	✓

NOISY:

Pump	2	✓
Column	2	✓
Non return to center	3	✓
Leaks at Check Stop	2	✓
Excessive Bound or Roll	3	✓

BODY INTEGRITY

Door Rattle	2	✓
Door Latch Performance	3	✓
Cowl Shake	2	✓
Excessive Noises	3	✓
Overall Integrity	3	✓

INSTRUMENT CHECK

SPEEDOMETER:

Excessive swing / bounce/ noisy	2	✓
---------------------------------	---	---

TRIP OR ODOMETER:

Non functioning	2	✓
-----------------	---	---

OIL PRESSURE:

High / low	2	✓
------------	---	---

TEMPERATURE:

High / low	2	✓
------------	---	---

AMP METER:

Discharging	2	✓
-------------	---	---

Other Indicators

	2	✓
--	---	---

TOTAL

SHELLY'S ROLLERS

DRIVING TEST

1

Owner Name: Curzon, Simon

Chassis Number: LRB15056

ENGINE:	Max Deduct		✓
Noisy	3		✓
Poor Performance / Misfire	5	1	✓
Smoke	3		✓
Leaks at "Check Stop"	2		✓

STEERING AND SUSPENSION	Max Deduct		✓
Feedback	2		✓
Excessive Play	5		✓
Knocks	2		✓

EXHAUST

Leaks	2		✓
Rattles or Knocks	2		✓

NOISY:

Pump	2		✓
Column	2		✓
Non return to center	3		✓
Leaks at Check Stop	2		✓
Excessive Bound or Roll	3	1	✓

DRIVE LINE

CLUTCH:

Ineffective	2		✓
Shudder	2		✓

BODY INTEGRITY

Door Rattle	2		✓
Door Latch Performance	3		✓
Cowl Shake	2		✓
Excessive Noises	3		✓
Overall Integrity	3		✓

GEARBOX / TRANSMISSION:

Poor shift	3		✓
Noisy	2		✓

PROP-SHAFT:

Noisy universal joints	2		✓
------------------------	---	--	---

REAR END:

Noisy / whine	2		✓
Drive dog clunk	2		✓

INSTRUMENT CHECK

SPEEDOMETER:

Excessive swing / bounce/ noisy	2		✓
---------------------------------	---	--	---

WHEELS / TYRES:

Rumble or thump	3		✓
Spokes / hubcaps	3		✓

TRIP OR ODOMETER:

Non functioning	2		✓
-----------------	---	--	---

BRAKES

Pulling to One or Other Side	5		✓
Noisy / Clunks	2		✓
Squeal	2		✓
Ineffective	5		✓
Excessive Pedal Travel	2		✓

OIL PRESSURE:

High / low	2		✓
------------	---	--	---

TEMPERATURE:

High / low	2		✓
------------	---	--	---

AMP METER:

Discharging	2		✓
-------------	---	--	---

Other Indicators *clock*

	2	1	✓
--	---	---	---

①

TOTAL

②

TOTAL

S. R. R. O. W. S. H. E. H. S.

DRIVING TEST

10/18

1

Owner Name: Curzon, Simon

Chassis Number: LRB15056

ENGINE:

	Max Deduct		✓
Noisy	3	1	✓
Poor Performance / Misfire	5		✓
Smoke	3		✓
Leaks at "Check Stop"	2		✓

STEERING AND SUSPENSION

	Max Deduct		✓
Feedback	2		✓
Excessive Play	5		✓
Knocks	2		✓

EXHAUST

Leaks	2		✓
Rattles or Knocks	2		✓

NOISY:

Pump	2		✓
Column	2		✓
Non return to center	3		✓

DRIVE LINE

CLUTCH:

Ineffective	2		✓
Shudder	2		✓

BODY INTEGRITY

Door Rattle	2		✓
Door Latch Performance	3		✓
Cowl Shake	2		✓
Excessive Noises	3		✓
Overall Integrity	3	1	✓

GEARBOX / TRANSMISSION:

Poor shift	3		✓
Noisy	2		✓

PROP-SHAFT:

Noisy universal joints	2		✓
------------------------	---	--	---

REAR END:

Noisy / whine	2		✓
Drive dog clunk	2		✓

INSTRUMENT CHECK

SPEEDOMETER:

Excessive swing / bounce/ noisy	2		✓
---------------------------------	---	--	---

WHEELS / TYRES:

Rumble or thump	3		✓
Spokes / hubcaps	3		✓

TRIP OR ODOMETER:

Non functioning	2		✓
-----------------	---	--	---

BRAKES

Pulling to One or Other Side	5		✓
Noisy / Clunks	2		✓
Squeal	2		✓
Ineffective	5		✓
Excessive Pedal Travel	2		✓

OIL PRESSURE:

High / low	2		✓
------------	---	--	---

TEMPERATURE:

High / low	2		✓
------------	---	--	---

AMP METER:

Discharging	2		✓
-------------	---	--	---

Other Indicators

	2		✓
--	---	--	---

54
TOTAL

46
TOTAL

S
H
O
R
O
N
S
U
C
O
M
P
R
E
S
S
E
D
S
H
E
E
T